

ARCHITECTURAL REVIEW BOARD

REGULAR MEETING ~ AGENDA ~

Shelley M. Kozlowski, Clerk of Council http://www.townofhaymarket.org/

15000 Washington Street, Suite 100 Haymarket, VA 20169

Wednesday, February 21, 2018

7:00 PM

Council Chambers

I. Call to Order

II. Pledge of Allegiance

III. Minutes Approval

1. Architectural Review Board - Regular Meeting - Jan 17, 2018 7:00 PM

IV. Citizens' Time

V. Certificate of Appropriateness

- 1. #ZP2018-003 Shoppes of Haymarket Sign Application
- 2. #ZP2018-004 6760 Madison Street
- 3. #ZP2018-005 6761 Madison Street, Fence Application
- 4. #ZP2018-006 Little Free Library

VI. Old Business

- 1. 6748 Bleight Drive Amendment to Fence Application
- 2. Haymarket Baptist Church Fence
- 3. #ZP2017-029 6810 Jefferson Street Demolition Application
- 4. Gateway Signs

VII. Adjournment



ARCHITECTURAL REVIEW BOARD

REGULAR MEETING ~ MINUTES ~

Shelley M. Kozlowski, Clerk of Council http://www.townofhaymarket.org/

15000 Washington Street, Suite 100 Haymarket, VA 20169

Wednesday, January 17, 2018

7:00 PM

Council Chambers

A Regular Meeting of the Architectural Review Board of the Town of Haymarket, VA, was held this evening in the Board Room, commencing at 7:00 PM.

Chair Kenneth Luersen called the meeting to order.

I. Call to Order

Chair Kenneth Luersen: Present, Councilwoman Susan Edwards: Present, Board Member Robert Day: Present, Board Member Bond Cavazos: Absent, Commissioner Madhusudan Panthi: Present.

II. Pledge of Allegiance

III. Citizens' Time

No Citizen's Comments.

IV. Minutes Approval

1. Architectural Review Board - Regular Meeting - Nov 15, 2017 7:00 PM

RESULT: ACCEPTED [UNANIMOUS]

MOVER: Susan Edwards, Councilwoman

AYES: Kenneth Luersen, Susan Edwards, Robert Day

ABSENT: Bond Cavazos

V. Certificate of Appropriateness

1. ZP#2017-029, 6810 Jefferson Street, Demolition Application

Mr. Dan Radtke, the Realtor representing the property owners, addressed the Commission. He briefly explained that the property was purchased by two sisters in 1985 and it has been vacant ever since. He stated that in early 2016 to late 2017 they decided to sell the property. He explained that one sister had passed without a Will delaying the property going onto the market. He continued by stating that they had originally thought that it was one parcel. However, after the Executor researched it, it was later revealed that there is a record plat that shows it is two parcels. He explained that the owners have recently had it re-certified with a survey and a plat was generated and recorded with the County as two lots. He does not know why the town was not notified of this. He continued by stating that the owners had an inspection done on the property and it was concluded that the house is in such disrepair there is no feasible way to restructure the property because the foundation is crumbling. He feels the best thing to do for the benefit of the community would be to take it down and build another house on the property. He concluded by stating that the builder, Mr. Cowne, has a contract on the property and is here tonight to answer any questions.

Mr. Panthi asked the size of the lot. Mr. Radtke responded that it approximately 0.6 acres total.

Chairman Luersen asked Mr. Radtke if they are planning on building on both lots or keeping it as one unit. Mr. Radtke replied that the plan is to build on both lots.

Councilwoman Edwards stated that there are only two houses left in the town that were built in this style and era. She expressed how upsetting it is when people purchase these historic homes and do not keep them maintained. She also shared concerns with the Town not being notified about the subdivision of the property and feels that more research needs to be done on this issue.

Chairman Luersen stated that this house is on the Haymarket Historic Registry. He said that the Board needs to gather some more information and get a better understanding of what the future concept of this property will be.

At this time, Pat Cowne addressed the Board. He explained that he just put the property under contract over the weekend. He stated that he pulled up the Architectural Review Board guidelines and ordinances for review. He stated that he is still looking at house plans at this time and plans to check in with Board before submitting something. He concluded by stating that they will be single family homes.

Mr. Day asked if his intentions were to build two houses and sell or rent them out. Mr. Cowne stated that they would probably rent them for a couple of years and then sell.

Councilwoman Edwards asked Mr. Cowne if there are access easement points to both lots. Mr. Radtke stated that there are no driveways on Jefferson Street. Mr. Cowne stated that he will have to get a grading plan for the residential entrances onto Jefferson Street. Ms. Lockhart interjected that they would have to front Jefferson. She also stated that there needs to be some clarification concerning how the lots were recorded and that she would work with the applicants. She continued by saying the Town's records have the parcel as one lot. She also noted that the Prince William Assessment Office has no record of it as two lots prior to June 23, 2017 when it was re-recorded.

Mr. Radtke invited members of the Board to come and visit the property. Councilwoman Edwards asked if the inspector of the property was a Structural Engineer. Mr. Radtke replied no, a Home Inspector. He further stated that the Structural Engineer that was contacted declined.

The Board concluded that they would like to get feedback from a Structural Engineer and more information on the plans for the property including placement on the property, square footage, and approximate size.

A motion was made to Table ZP#2017-029, 6810 Jefferson Street until the February 21, 2018 Architectural Review Board meeting.

RESULT: TABLED [UNANIMOUS]

MOVER: Susan Edwards, Councilwoman SECONDER: Robert Day, Board Member

AYES: Kenneth Luersen, Susan Edwards, Robert Day, Madhusudan Panthi

ABSENT: Bond Cavazos

2. ZP2018-001: Sign Application, 15100 Washington Street

Town Planner, Emily Lockhart, gave a brief description of the proposed sign that is in the Agenda packet.

A motion was made To Approve ZP#2018-001: Sign Application for 15100 Washington Street.

RESULT: ADOPTED [UNANIMOUS]

MOVER: Robert Day, Board Member

SECONDER: Susan Edwards, Councilwoman

AYES: Kenneth Luersen, Susan Edwards, Robert Day, Madhusudan Panthi

ABSENT: Bond Cavazos

3. ZP2018-002: Damaged Door Application, 15101 Washington Street

Ms. Lockhart stated the School of Rock's main front door is damaged and the stained glass windows are breaking. She further explained that they are having trouble closing the door. She continued by stating that they are looking to replace the door with a custom made door very

January 17, 2018

similar to what they currently have. She introduced Mary Hitchcock, of School of Rock to further explain in more detail.

Ms. Hitchcock addressed the Board. She explained that she has hired a contractor to replace the door. She stated that they are using the exact same door and color and reapplying the original bell in the door. She said that the only thing that will be different is the hardware and door knob but they are trying to match it as close as possible. Ms. Hitchcock further explained that they are having trouble finding the stained glass windows. She stated that her contractor recommended using clear glass at this time and covering it with stained glass later. Ms. Hitchcock emphasized that she needs to move on sealing the glass door now because there are existing sharp edges on the glass and children could hurt themselves.

Councilwoman Edwards asked if she would come back if the pattern is different. Ms. Hitchcock stated that she would not be able to find the exact same pattern. She stated that she will try and replace it but if she could not, would it be okay to leave the clear glass. Mr. Day said that he would prefer it to be the stained glass and that he has a some contacts that he could forward to her.

A brief discussion ensued concerning perhaps donating the original door to the museum.

A motion was made by Councilwoman Edwards to approve ZP#2018-002 with the condition when the stained glass is contracted that Ms. Hitchcock come back for approval. The motion was seconded by Board member Robert Day.

After discussion, the original motion was amended to add a 90 day time limit to come back with a rendering for the stained glass.

RESULT: ADOPTED [UNANIMOUS]

MOVER: Susan Edwards, Councilwoman

SECONDER: Robert Day, Board Member

AYES: Kenneth Luersen, Susan Edwards, Robert Day, Madhusudan Panthi

ABSENT: Bond Cavazos

VI. Town Council Update

Councilwoman Edwards stated that the January Town Council meeting was postponed til tomorrow. Chairman Luersen asked about the Christmas Celebration. Councilwoman Edwards stated that it was a little icv but very nice.

Ms. Lockhart stated the Meladon Group will not be able to present at the Town Council meeting tomorrow night but she has a diagram of what they are proposing if anyone would like to view it. She further stated that they are looking to come to the Architectural Review Board to do a design guideline packet. Councilwoman Edwards asked Ms. Lockhart to share with the Board some developments they have already done. Ms. Lockhart stated that they were the developers for the Cascades and are looking to model the Fairground property after the Gateway development in Purcellville.

Councilwoman Edwards stated that the Town Council is firming up plans on redoing the exterior of the building.

Chairman Luersen asked about the status of the pathway from the bridge up to the corner of Jefferson Street. Ms. Lockhart believes that it is still going on as planned.

VII. Planning Commission Update

Chairman Luersen introduced the new Planning Commission Liaison, Commissioner Mahdu Panthi.

Commissioner Panthi updated the Architectural Review Board on the Planning Commission. He stated that "A Dog's Day Out" was referred to the Town Council with Planning Commission's approval.

VIII. New Business

Ms. Lockhart stated that someone from Prince William County reached out to the staff about doing a possible walking tour of the town showcasing the history of the town. There will be a meeting with Staff if anyone would like to attend the meeting.

IX. Old Business

Councilwoman Edwards stated that she will be reaching out to Steve Shannon on the placement of the Gateway signs. She also stated that the Town had an Historic Commission that is no longer active. She further explained that there is a good amount of money in an account for streetscape needs such as planters and lights. She concluded by stating that they are working on getting access to that money to finish up projects in the Town that were suppose to be done.

Commissioner Panthi asked if there was any kind of State or Federal funding for the Town. Ms. Lockhart stated that there is a Main Street Program. She explained that Haymarket is too small but that we could be a Main Street affiliate. She stated that she will look into it further.

X. Adjournment

1. Motion to Adjourn

RESULT: ADOPTED [UNANIMOUS]

MOVER: Susan Edwards, Councilwoman

SECONDER: Robert Day, Board Member

AYES: Kenneth Luersen, Susan Edwards, Robert Day, Madhusudan Panthi

ABSENT: Bond Cavazos

Submitted:	Appro	Approved:		
Shelley M. Kozlowsk	ki, Clerk of the Council	Kenneth Luersen, Chairman		



Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner

DATE: February 14, 2018

SUBJECT: Zoning Permit #2018-003, Shoppes at Haymarket Sign Permit Application

APPLICANT INFORMATION:

The applicant, Shoppes at Haymarket, LLC is applying for a freestanding menu sign. The sign will be located within a sign easement on the McDonald's property. Please see attached picture and plat for location. The sign details are as follows;

Type: Freestanding menu sign

Height Above Ground: Lower Edge 2 feet Upper Edge 8 feet Height of Sign Structure: 8 feet *not including the finials*

Sign Width: 6 feet Sign Length: 6 feet Sign Area: 36 feet Number of Faces: 2

Sign Material: Aluminum, acrylic

Color: Green

Font: Californian FB

Location: See attached photo

Lighting: Solar LED lights to be added later, external lights placed on the ground

The sign meets the standards and guidelines put forth by the ARB. The maximum square footage for a permitted sign in this zoning district is 36 square feet, which has been met with the proposed sign.

STAFF RECOMMENDATION:

The proposed sign meets the Town's Historic Guidelines and conforms with the Town Zoning Ordinance. This sign is in keeping with the other menu signs located along Washington Street. Staff feels that the sign has met all requirements and should be approved upon review by the ARB.

DRAFT MOTION:

"I make a motion to approve Certificate of Appropriateness ZP#2018-003 for the Shoppes at Haymarket to place a freestanding menu sign with their sign easement on Washington Street."

Or An alternate motion.



paid 02/08/201

ZONING PERMIT #: 2018-003

NOTE: This application must be filled out to the state of
NOTE: This application must be filled out completely and all components of submission requirements must be met before the application can be accepted and scheduled for review/hearing.
(Check all that apply) New Tenans (Lease Construction Check all that apply) New Tenans (Lease Construc
NAME OF BUSINESS/APPLICANT: Shoppes At Hashmark to 100 (See Spec sheet)
PROPOSED LICE. Should not a series to the first the firs
SITE ADDRESS: 15201 116 56:01 STATE INSTRUCTION: 60 X 6W X12 d
Subdivision Name: Space of Hard Park I Faller 10 #: 12/8 10 9353
ZONING DISTRICT: DR-1 DR-2 DR-1 DR-2 Transfer DR-1 DR-2 DR-1 DR-1 DR-2 DR-1 DR-1 DR-2 DR-1 DR-1 DR-1 DR-1 DR-1 DR-1 DR-1 DR-1
Special Use Decreit Description of the Property of the Propert
Off-street Parking: Spaces Required: 302 Spaces Provided: 325
DESCRIPTION OF ACTIVITY: (i.e. previous use height/length of first
Signs per the attached plans and specification
, , , , , , , , , , , , , , , , , , , ,
Supporting Documentation (attached): Narrative Plan/Plat Specification Sheet
Narrative Milan (Disched):
Carlot Control of the
EXTREMAND CONTRACTOR
CEMPTICATES OF APPRIOURING THE CO
EXTREMAND CONTRACTOR
ADDITIONAL DESCRIPTION: (i.e. color, type of material, font style, etc. See Sign Spec Sheet for Signage detail)
ADDITIONAL DESCRIPTION: (I.e. color, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s)
ADDITIONAL DESCRIPTION: (I.e. color, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION
ADDITIONAL DESCRIPTION: (I.e. calor, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION PROPERTY OWNER INFORMATION
ADDITIONAL DESCRIPTION: (I.e. color, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION Supposes at Hadranket LLC Name Name Name
ADDITIONAL DESCRIPTION: (I.e. color, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION Supposes at Hadranket LLC Name PO Box 1146 Address Note: See Sign Spec Sheet for Signage detail) Property Owner Information Name 10813 Codas Crack Dr.
ADDITIONAL DESCRIPTION: (I.e. color, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION Supposes at Hadranket LLC Name PO Box 1146 Address Taylanket Uff 20168 See Sign Spec Sheet for Signage detail) Property Owner Information Name 18813 Cadar Crack Dr. Address
ADDITIONAL DESCRIPTION: (I.e. calor, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION PROPERTY OWNER INFORMATION Teral 4 Patricia Leaberry Name PO Bax 1146 Address LOSIS Cadar Creek Dr. Address Laymarket, UR 20168 Specification Sheet Photograph(s) PROPERTY OWNER INFORMATION Name LOSIS Cadar Creek Dr. Address Specification Sheet Photograph(s) PATRICIA Patricia Leaberry Name LOSIS Cadar Creek Dr. Address State Zip State Zip
ADDITIONAL DESCRIPTION: (I.e. calor, type of material, font style, etc. See Sign Spec Sheet for Signage detail) Supporting Documentation (attached): Specification Sheet Photograph(s) PERMIT HOLDER INFORMATION Shappes at Hadranket LLC Name PO Box 1146 Address Taylonaket, UA 20168 Spate Vivernia, UA 23551 City State To State

PAGE


- And the second of the second		
de commence de la frança de de forma de la companya de la companya de la companya de la companya de la company		

Attachment: #ZP2018-003 Shoppes at Haymarket (3483: #ZP2018-003 Shoppes of Haymarket Sign Application)

APPLICANT /	PROPERTY OWNE	R SIGNATURE	******REQUIRED*****
and as shown and any add Commission, a	on the attached planitional restrictions or the Town Council of	t, plan and/or specifications and/or conditions prescrib and all other applicable laws	cel, do hereby certify that I have the authority to make the is correct. Construction of improvements described herein will comply with the ordinances of the Town of Haymarket
		***OFFICE US	
Date Filed:		Fee Amount:	Date Paid:
DATE TO ZO	ONING ADMINIS	TRATOR:	
□APPROVED	DISAPPROVED	TABLED UNTIL:	DEFERRED UNTIL:
CONDITIONS:		SIGNATURE	PRINT
DATE TO AF	RCHITECTURAL F	REVIEW BOARD (ARB)	
□ APPROVED	DISAPPROVED	OTABLED UNTIL:	DEFERRED UNTIL:
CONDITIONS:		SIGNATURE	PRINT
		F APPLICABLE):	
DAPPROVED	DISAPPROVED	TABLED UNTIL:	DDEFERRED UNTIL:
CONDITIONS:	L (where required):	SIGNATURE	PRINT

SIGN SPECIFICATION SHEET

		not including	1 Finials
SIGN 1:			1 1 1 1 1 1 1 1 1 1 1
Type of Sign: Dwall DHanging Freestanding Double Sided Mehu Si	an		□Window
Height above Ground at Signs: Lower Edge: 2FF	Upper Edg	ge: 8 Ft	
Height of Sign Structure: 8 Ft Sign Width: 6 Ft	_ Length:(6 Ft Area in Sq Ft	:_36
Number of Faces: Sign Material/Color/Font:_	Aluminun	n , acryrl / Gree	en
Location of Sign (Include photo): Highway C	whie D	Shappes at Ho	ymacket fo
Lighting Type/Fixture (No internal illumation is allowed		/LED Lights	Add latter
Front Style - Cali Forni	an FB		
SIGN 2:			
Type of Sign: □Wall □Hanging □Freestanding □Other	□Menu	□Individual Letter	□Window
Height above Ground at Signs: Lower Edge:	Upper Edg	e:	
Height of Sign Structure: Sign Width:			:
Number of Faces: Sign Material/Color/Font:_			
Location of Sign (Include photo):			
Lighting Type/Fixture (No internal illumation is allowed)):		
SIGN 3:			
Type of Sign: □Wall □Hanging □Freestanding □Other	□Menu	□Individual Letter	□Window
Height above Ground at Signs: Lower Edge:	Upper Edge	e:	
Height of Sign Structure: Sign Width:	Length:	Area in Sq Ft:	
Number of Faces: Sign Material/Color/Font:_	10		
Location of Sign (Include photo):			
Lighting Type/Fixture (No internal illumation is allowed)	:		
SIGN 4:			
Type of Sign: □Wall □Hanging □Freestanding □Other			□Window
Height above Ground at Signs: Lower Edge:	Upper Edge	e:	 -
Height of Sign Structure: Sign Width:	Length:	Area in Sq Ft:	
Number of Faces: Sign Material/Color/Font:_			
ocation of Sign (Include photo):			
ighting Type/Fixture (No internal illumation is allowed).	:		



moo.sngissanaska.www



Please check for correct spelling, numbers, names, etc.
Shane's Signs is not responsible for errors once signed proof is returned.
17015 Gaines Road, Broad Run, VA 20137 • p: 703-753-3016 • f: 703-753-3176


Packet Pg. 11



Post & Panels (Powder Coat Finish)

Discounts available for multiple kit orders.


RTS - Post & Panel System



Plagmount

(2 Posts Required)

Double Post Mount



Double Post Mount (3-1/4" Square Post shown)


Note: All mounting provisions to be provided by fabricator.

3-1/4" Square Post $(\times 2.)$

3-1/4" Round Post









Available in gloss white and gloss black powder coated finishes, 96" and 144" posts. Each 96" and 144" RTS Post Kit includes:

- 48" slot to accommodate up to a 48" high, 1/8" or 3mm panel.
- One (1) adjustable, 48" aluminum Post Filler to accommodate a panel less than 48" high.
- One (1) 1/8" aluminum Post Cap with countersunk cap screws.
- One (1) 96" aluminum, adjustable Panel Trim for 3mm hollow core panel material.
- · Two (2) 6" Locking Strips.
- One (1) 96" or 144" RTS Post powder coated black or white Gloss Finish.


NOTE: Face material not included.

List Price Per Single Post (2 posts required for double post mount)

Optional Accessories



Ball Finial Kit w/Square Cap White - Part #RTS-5700F WHIT Black - Part #RTS-5700F BLK



Ball Finial Kit w/Round Cap White - Part #RTS-5701F WHIT Black - Part #RTS-5701F BLK



Tapered Ring Finial Kit W/Round Cap White - Part #KTS-\$703F WH'T Black - Part #RTS-\$703F BLK



Tapered Ring Finial Kit W/Square Cup White - Part #RTS-5702F WHT Black - Part #RTS-5702F BLK

Square Post

96" Post Part #RTS-1015-8 WHT Part #RTS-1015-8 BLK

point steer

144" Post

Par: #RTS-1015-12 WHT Part #RTS-1015-12 BLK

Round Post

96" Post Pa t #RTS-1017-8 WHT Part #RTS-1017-8 BLK

144" Post Par: #RTS-1017-12 WHT Pa t #RTS-1017-12 BLK

Ball Finial

Ball l'inial with Square Cap (Cap Screws and Threaded Insett Inchide) Part #RTS-5700F WHT Part #RTS-5700F BLK

Ball Finial with Round Cap Cap S. reswa and Threaded Insert Include Pr rt #RTS-5701F WHT Part #RTS-5701F BLK

NOTI : Caps are slightly oversized.

Tapered Ring Finial

Tapered Ring Finial with Square Cap (Cup S rews and Threaded Insert included) Part #RTS-5702F WHT Part #RTS-5702F BLK


Tapered Ring Finial with Round Cap Part #RTS-5703F WIIT Part #RTS-5703P BLK


NOTE: Caps are slightly oversized.


Finial Kit Includes: Finial with 1/4" threaded stud, Cap with 1/4" threaded insert and two (2) Cap Screws.

3032 Walker Ridge Dr. N.W ▶ Grand Rapids, MI ▶ Phone: (616) 784-0405 ▶ Toll Free: (877) 784-0405 ▶ 1 ax: (616) 784-0411











Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner

DATE: February 14, 2018

SUBJECT: Zoning Permit #2018-004, Updates and Approval Request for 6760 Madison Street

APPLICANT INFORMATION:

The applicant, Rosanna Smith is attending the meeting to give the ARB updates on the home restoration at 6760 Madison Street. In addition to the updates Ms. Smith will be presenting several items for approval. The items are as follows;

- Replace the existing porch roof with a new standing seam metal roof to match the rest of the home
- Request to place a fixed window in the gable in lieu of the vent as pictured in the application package. The need for a vent has been eliminated by the new roof. The window would be similar to the other existing windows. This window would be approximately 20" by 30" and would not open.
- Request to place 2 recessed lights in the beadboard ceiling of the front porch
- Request to place 2 matching wall mounted lights on either side of the front door. See application packet for styles. The applicant is requesting both light styles be approved so that they have an option after seeing them in person.

The requests proposed by the applicant are reasonable and fall within the Guidelines set forth by the Town.

STAFF RECOMMENDATION:

Staff feels that the requested modifications and changes have met all requirements and should be approved upon review by the ARB.

DRAFT MOTION:

"I make a motion to approve Certificate of Appropriateness ZP#2018-004 for 6760 Madison Street to replace the porch roof, replace the gable vent with a window and install lighting on the porch and at the front door."

Or An alternate motion.



ZONING PERMIT APPLICATION

ZONING PERMIT #: 2018-004

NOTE: This application must be filled out completely and all components of submission requirements must be met before the application can be accepted and scheduled for review/hearing.

ZONING ACTIVITY: □ New Construction ☐ Alteration (Check all that apply) □ New Tenant/Use □ Change	on/Repair
NAME OF BUSINESS/APPLICANT: hosana	& Kevin Smith
PROPOSED USE:	Size (Sq. Ft./Length) of Construction:
SITE ADDRESS: 6760 Madison St	Yelt Parcel ID #:
Subdivision Name:	Lot Size:
ZONING DISTRICT: ☑ R-1 ☐ R-2 ☐ B-1 ☐ B-2	□ -1 □ C-1
Special Use Permit Required: 🔲 Yes 🕱 No	Site Plan Required: 🗖 Yes 🕱 No
Off-street Parking: Spaces Required:	Spaces Provided:
BRIEF DESCRIPTION OF ACTIVITY: (i.e. previous use, he	그리 그 그리 (1977) - 하시 - 하
= Replace existing parch room Place 2 recessed lights, a	
Supporting Documentation (attached): Marrative 🗆	Plan/Plat ☐ Specification Sheet (+) Photos
FEE: 🗹 \$25.00 Residen	tial 🗖 \$50.00 Commercial
CERTIFICATE OF A	APPROPRIATENESS
ADDITIONAL DESCRIPTION: (i.e. color, type of material, See attached nouvative a	
Supporting Documentation ($attached$): \square Specification	Sheet ☐ Photograph(s)
PERMIT HOLDER INFORMATION	PROPERTY OWNER INFORMATION
Name	Name
Address	Address
City State Zip	City State Zip
Phone# Email	Phone# Email

Packet Pg. 18

I, as owner or authorized agent for the above-referenced parcel, do hereby certify that I have the authority to make the foregoing application and that the information provided herein is correct. Construction of improvements described here and as shown on the attached plat, plan and/or specifications will comply with the ordinances of the Town of Haymark and any additional restrictions and/or conditions prescribed by the Architectural Review Board (ARB), Plannin Commission, or the Town Council and all other applicable laws. Applicant Signature Property Owner Signature ***OFFICE USE ONLY*** Date Filed: 02 Perperty Owner Signature ***OFFICE USE ONLY*** Date Filed: 02 Date Paid:	APPLICANT / PROPERTY OWNE	R SIGNATURE	*****REQUIRED*****
OFFICE USE ONLY Date Filed: 02	foregoing application and that the and as shown on the attached pla and any additional restrictions	ninformation provided her t, plan and/or specificatio and/or conditions presci	ein is correct. Construction of improvements described herein ns will comply with the ordinances of the Town of Haymarket ribed by the Architectural Review Board (ARB), Planning
Date Filed: 02 Fee Amount: \$25.00 Date Paid: DATE TO ZONING ADMINISTRATOR: 02 09 20 8 DAPPROVED DISAPPROVED DISA	Applicant Signature		Property Owner Signature
DATE TO ZONING ADMINISTRATOR:		***OFFICE U	SE ONLY***
DATE TO ZONING ADMINISTRATOR:	Date Filed: 02	Fee Amount: \$25.	OO Date Paid:
SIGNATURE PRINT CONDITIONS: DATE TO ARCHITECTURAL REVIEW BOARD (ARB): DAPPROVED DISAPPROVED TABLED UNTIL: DEFERRED UNTIL: SIGNATURE PRINT CONDITIONS: DATE TO TOWN COUNCIL (IF APPLICABLE): DEFERRED UNTIL: DEFERRED UNTIL: PRINT TOWN COUNCIL (where required): SIGNATURE PRINT			
DATE TO ARCHITECTURAL REVIEW BOARD (ARB): DATE TO ARCHITECTURAL REVIEW BOARD (ARB): DATE TO ARCHITECTURAL REVIEW BOARD (ARB): SIGNATURE PRINT DATE TO TOWN COUNCIL (IF APPLICABLE): DATE TO TOWN COUNCIL (IF APPLICABLE): DATE TO TOWN COUNCIL (Where required): SIGNATURE PRINT			
□APPROVED □DISAPPROVED □TABLED UNTIL: □DEFERRED UNTIL: □	CONDITIONS:	SIGNATURE	PRINT
SIGNATURE PRINT CONDITIONS: DATE TO TOWN COUNCIL (IF APPLICABLE): DAPPROVED DISAPPROVED TABLED UNTIL: TOWN COUNCIL (where required): SIGNATURE PRINT	DATE TO ARCHITECTURAL I	REVIEW BOARD (AR	B):
DATE TO TOWN COUNCIL (IF APPLICABLE): APPROVED DISAPPROVED TABLED UNTIL: TOWN COUNCIL {where required}: SIGNATURE PRINT	□APPROVED □DISAPPROVED	□TABLED UNTIL:	□DEFERRED UNTIL:
□APPROVED □DISAPPROVED □TABLED UNTIL: □DEFERRED UNTIL: □	CONDITIONS:	SIGNATURE	PRINT
TOWN COUNCIL {where required}: SIGNATURE PRINT	DATE TO TOWN COUNCIL (I	F APPLICABLE):	
SIGNATURE PRINT	□APPROVED □DISAPPROVED	□TABLED UNTIL:	DEFERRED UNTIL:
	TOWN COUNCIL (where required):	SIGNATURE	DDINT
CONDITIONS:	CONDITIONS:	SIGNATURE	PKINI

Requests for Approval -Updates and Lighting-

for

6760 Madison St Haymarket, VA

Respectfully Submitted to the Haymarket ARB on Feb 9th, 2018

Owners: Rosanna & Kevin Smith

Talent: Tom & Nathan Vetter

Since our last ARB meeting (April 2017), we have made considerable progress at 6760 Madison, and we appreciate your support to that end. The overall goal remains the same: To return the original house to its wood-sided, metal roofed condition, while adding on an extended second floor in keeping with the historic design of the house.


As is often the case with old homes, we have made discoveries that have resulted in significant delays and extra expense. However, the house has also given us delightful surprises, such as old wall paper remnants, bullet casings near the original front porch (now the back), a few old bottles, and one of the best surprises - wood floor boards thick enough to re-condition and place back inside the house to help tell its story for generations to come. With the care we are taking, we expect 6760 Madison to stand proudly as a humble farmhouse for at least another 120 years.

#1 Exterior - PORCH ROOF:


Updated - We request permission to replace the current porch roof with a new standing seam metal roof to match the rest of the home. We originally wanted to keep the old metal roof, but have since observed that it would be a fresher look overall to replace it a new version of the original.

#2 Exterior - GABLE VENT:

Updated – We request permission to place a fixed window in the gable in lieu of the vent as pictured below. The new metal roof is already vented at both ends, eliminating the need for the vent. A window, of the same manufacturer and likeness as the other windows of the house would allow for natural light to enter.



Same as the rest of the windows, but does not open and would measure approximately 20" wide x 30" tall, proportional to the space.



#3 Exterior – PORCH LIGHTS:

We request permission to have 2 recessed lights in the beadboard ceiling of the front porch. In addition, we request permission to place two matching wall mounted lights on either side of the front door. We feel both styles below could be an appropriate fit for the home and request approval for both so that we can make our decision based on trying them "in person".



Forte Lighting 17003-01-04 Black Energy Efficient Fluorescent 4.5Wx10.5Hx6E Outdoor Wall Sconce

Traditional / Classic Outdoor Wall Sconce

- •4.5W x 10.5H x 6E
- ·Energy Star
- •1-13 Watt PLS
- •Features Satin White Glass Panels



Park Harbor PHEL1000ANPE Antique Pewter Portsmouth 9" Tall Single Light Outdoor Wall Sconce

- •Item # bci2852486
- •Model # PHEL1000ANPE
- •8"W x 9.13"H
- •Extension: 9.5" (measured from mounting surface to furthest protruding point on fixture)
- Backplate Height: 5"
- Backplate Width: 5"
- •HCO: 5" (height from center of outlet)



Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner

DATE: February 14, 2018

SUBJECT: Zoning Permit #2018-005, 6761 Madison Street

APPLICANT INFORMATION:

The applicant, Jason Scott is applying for a Zoning Permit for a fence at 6761 Madison Street. Mr. Scott will be installing 238' linear feet of 48" high yellow pine picket fence. An 8' gate will be installed on the north side of the home along the driveway. The fence will run along the property line and extend across the back meeting up with the neighbor's existing fence. See the attached application for the complete sketch.

The request proposed by the applicant has met the Guidelines set forth by the Town.

STAFF RECOMMENDATION:

The proposed fence meets the Guidelines set forth by the ARB. The style and color are consistent with the neighboring property owner's fence, which the new fence will join up against. Staff recommends approval of the application.

DRAFT MOTION:

"I make a motion to approve Certificate of Appropriateness ZP#2018-005, for the proposed fence at 6761 Madison Street."

Or An alternate motion.



ZONING PERMIT APPLICATION

ZONING PERMIT #: 2019-005

NOTE: This application must be filled out completely and all components of submission requirements must be met before the application can be accepted and scheduled for review/hearing.


,		
ZONING ACTIVITY: Thew Construction Altera (Check all that apply) New Tenant/Use		
NAME OF BUSINESS/APPLICANT: JASON SO	N. 70	
PROPOSED USE: FENCE		q. Ft./Length) of Construction: 238 /
SITE ADDRESS: 6761 MPOISON ST.		
Subdivision Name:		Lot Size:
ZONING DISTRICT: ☑ R-1 ☐ R-2 ☐ B-1 ☐ B-2	□ I-1 □ C	0-1
Special Use Permit Required: 🔲 Yes 🖵 No		Site Plan Required: 🔲 Yes 🖵 No
Off-street Parking: Spaces Required:		Spaces Provided:
BRIEF DESCRIPTION OF ACTIVITY: (i.e. previous use,		
INSTALL 238' DR 48" HIGH YELLS		
GATE ON ABOUTH SIDE OF HOUSE, FE		
TO REBA CORNER AND BEROSS REAR YARD OFFICE OF HELD WELL	TO EXIST	TWE NIGHER'S FINEE. ADDI'L 48" F.
Supporting Documentation (attached): Warrative	<i>e HBa⊾'s P</i> ⊒∕Plan/Plat	Specification Sheet
	-	20 12 November 20 20 20 20 20 20 20 20 20 20 20 20 20
FEE: ☐ \$25.00 Reside	ential 🔲 \$5	50.00 Commercial
CERTIFICATE OF	APPR	OPRIATENESS
ADDITIONAL DESCRIPTION: (i.e. color, type of materi	al, font style,	etc. See Sign Spec Sheet for Signage detail)
YELLOW PINE FENCE		
	Cl D	District and (a)
Supporting Documentation (attached): Specification	on Sneet 🛄 i	Photograph(s)
PERMIT HOLDER INFORMATION	PROPERTY O	OWNER INFORMATION
JASON SCOTT		eme
Name	Name	
6761 MADISON ST.	0.44	
Address	Address	
City State 7in	City	State Zip
Address HAYMARKET IA ZO167 City State Zip 703-350-1085 jasenscott 7110 Phone# Email Gmail.com	U.L.J	2.50
Phone# Email 9mail.com	Phone#	Email

APPLICANT /	PROPERTY OWN	ER SIGNATU	IRE	*****REQUIRED*****
foregoing app and as shown and any add	dication and that the on the attached pla litional restrictions or the Town Council of the Town	e information at, plan and/o and/or cond	n provided herein is conspecifications will ditions prescribed by applicable laws.	Io hereby certify that I have the authority to make the correct. Construction of improvements described herein comply with the ordinances of the Town of Haymarket by the Architectural Review Board (ARB), Planning of the County of the Architectural Review Board (ARB), Planning of the County of the Architectural Review Board (ARB), Planning of the County of the Coun
			OFFICE USE C	
Date Filed:	2/13/2019	Fee Amour	nt: \$25.00	Date Paid: 02/13/2018
DATE TO ZO	ONING ADMINI	STRATOR:	02/13/20	118
Approved Applicat	ion has ma	of the	ENHALL V	DEFERRED UNTIL: DOCKHAEL PRINT by the Town, The
DATE TO AF	RCHITECTURAL	REVIEW B	OARD (ARB): ()	2/21/2018
□APPROVED	DISAPPROVED	☐TABLED (JNTIL:	☐DEFERRED UNTIL:
CONDITIONS:			SIGNATURE	PRINT
DATE TO TO	DWN COUNCIL (IF APPLICA	ABLE):	
	5			
□APPROVED	DISAPPROVED		JNTIL:	☐DEFERRED UNTIL:
TOWN COUNCI	L (where required):		SIGNATURE	PRINT
CONDITIONS:				
the state of the s				



44330 Mercure Circle | Suite 140, Dulles VA 20166 Office (703) 820-0967 Fax (703) 661-8610 CL# 2705078833A | MD Lic.# 127411

www.buildersfenceco.com



(Authorized Representative's Signature)


Jeffrey A. Cederborg

(Signature)


(Signature)


Date
















Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart
TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner

DATE: February 14, 2018 SUBJECT: Little Free Library

APPLICANT INFORMATION:

Casey Rives has approached Town Hall and has offered to donate a Little Free Library to our Town. Please read Ms. Rives letter attached for more details about the project. She is very excited about the opportunity and what the library can do for our community.

The ARB should review the pictures provided by Ms. Rives so that we can give guidance on the aesthetics of the structure. The Town Staff would like to see the structure placed at the Museum courtyard near the benches. We feel that at this time it would be an ideal location for keeping an eye on the structure, it would be in a high traffic area, and children could even sit on the benches and read at the site. Hopefully, in the future we can place another structure at the park.

Ms. Rives has outlined in her letter her intent to provide the structure, care and maintenance. The Town Staff will work with Ms. Rives on the details of the long-term care.

STAFF RECOMMENDATION:

The proposed Little Free Library is a great way to engage our community. Staff is excited that Ms. Rives has approached the Town with this idea and generosity. The ARB should give guidance on the preferred style of the structure. For example, the structure could resemble the basic structure of the museum and keep consistent colors.

DRAFT MOTION:

"I make a motion to approve Certificate of Appropriateness ZP#2018-006, for the proposed Little Free Library following the conditions and requirements set forth by the ARB."

Or An alternate motion.



ZONING PERMIT APPLICATION

ZONING PERMIT #: 2018-006

	tely and all components of submission requirements must be met accepted and scheduled for review/hearing.
ZONING ACTIVITY: ■New Construction □Alte	
NAME OF BUSINESS/APPLICANT: Casey Rives	
PROPOSED USE: Donation of a Little Free Lib	orary Size (Sq. Ft./Length) of Construction:
SITE ADDRESS: Location per Town's prefere	
Subdivision Name:	
ZONING DISTRICT: □ R-1 □ R-2 ■ B-1 □ E	
Special Use Permit Required: ☐ Yes ☐ No	Site Plan Required: ☐ Yes ☐ No
Off-street Parking: Spaces Required:	Spaces Provided:
to engage children in reading. The structure vertical materials to match the Town. Pictures attached Supporting Documentation (attached): Narrative	
CERTIFICATE O	F APPROPRIATENESS
approximately 5' tall - co	erial, font style, etc. See Sign Spec Sheet for Signage detail) 10r SChomo, to match that of incs or perhaps the Police Dept's Renatural wood Structure tion Sheet Photograph(s)
PERMIT HOLDER INFORMATION Casey Rives	PROPERTY OWNER INFORMATION Town of Haymarket
Name 14191 Hunters Run Way	15000 Washington Street, Suite 100
Address Gainesville VA 20155	Address Haymarket VA 20169
City State Zip	City State Zip
703-887-8666	703-753-2600 elockhart@townofhaymarket.
Phone# Email	Phone# Email

APPLICANT / P	PROPERTY OWNE	R SIGNATU	RE	**:	****REQUIRED*****
foregoing applic and as shown of and any additi	cation and that the n the attached plac ional restrictions the Town Council o	information t, plan and/oi and/or cond	provided here r specification itions prescri applicable law	ein is correct. C is will comply t ibed by the	y certify that I have the authority to make the Construction of improvements described herein with the ordinances of the Town of Haymarke Architectural Review Board (ARB), Planning er Signature
Applicant oignat				Tope (1, g)	
		***0	FFICE U	SE ONLY	***
Date Filed:	26/2018	Fee Amoun	t:		Date Paid:
DATE TO ZOI	NING ADMINIS	STRATOR:	1126/1	8	
 ✓ APPROVED	□DISAPPROVED	□TABLED U	JNTIL:	,	DEFERRED UNTIL:
			EMU SIGNATURE	il I	Lockhus
Set of DATE TO ARC	the requirements	Ita A	nents RB S DARD (ARE	and sign ac stran	recommendations recommendations ce & care.
□APPROVED	□DISAPPROVED	□TABLED U	INTIL:		DEFERRED UNTIL:
CONDITIONS:			SIGNATURE		PRINT
DATE TO TO	WN COUNCIL (IF APPLICA	ABLE):		
□APPROVED [□DISAPPROVED	☐TABLED U	NTIL:		DEFERRED UNTIL:
TOWN COUNCIL	(where required):				
CONDITIONS:		<u> </u>	SIGNATURE		PRINT
	-				

Casey Rives
14191 Hunters Run Way
Gainesville, VA 20155
703-887-8666
crives@fairfaxcounty.gov
January 26, 2018

Town of Haymarket
Architectural Review Board
15000 Washington St, Suite 100
Haymarket, VA 20169

Dear Town Of Haymarket Review Board,

I am excited about the possibility of donating a 'Little Free Library' to our beautiful small town. I understand the importance of the review board and would like to provide more detailed information about my goals and hopes for this pending structure.

As a public safety employee, shift work allows me the ability to travel often. Several times, I have come across 'Little Free Libraries' which sparked my interest in creating one for our town. The structure itself would be registered on Littlefreelibary.org which provides a logo sticker for the box and a system which allows the library to be posted on a world map to show where all libraries are located.

The purpose of this library would be to provide free reading material with no obligation to the children (and adults) in our community. Success rates in school rapidly increase when a child has access to books. In addition, this will create a hassle-free way to access books with no worries about late fees, library cards, time limits, etc. Children can also learn the importance of sharing, by swapping a book for one they have already read—exchanging books throughout the library system is one of the great benefits of the free library!

To keep children engaged, I will add a small mailbox slot where people can suggest books they want to read, letters/drawings about books they have read and any suggestions they may have.

The location of the library is perhaps the most important aspect of it and with the town's approval, it would be ideal to have it placed in a high foot-traffic area. With the small businesses, restaurants and ice cream shops throughout the town—this would be a great thing for children to walk to for an adventure of their own during a family outing. Kids in today's society need more reasons to explore, to be outside and to engage themselves in activities that spark imagination or build a relationship with their community!

Town of Haymarket January 26, 2018 Page 2

As a previous journalist for Prince William Living, I will provide a small write-up about the library to help market it prior to placement. This would be posted in local media outlets, such as, InsideNOVA, Bull Run Observer and other local magazines or newspapers. In addition to the above, I will create a Haymarket Little Library social media page to keep children and parents involved. This would also be a great way to further engage children, such as, having Girl Scout/Boy Scout Troops or local classrooms care for the structure on occasion!

For overall care, I plan to provide the initial structure, made with materials and paint that represent the town. In addition to the initial structure, I will maintain the appearance of the library and provide materials for it throughout the years and designate backup stewards in case of emergencies.


I truly believe that adding a free library to the Town Of Haymarket would be beneficial to our community and help maintain the 'small town' feel that so many residents love about the area. I thank you all sincerely for your time and consideration during this process!

Sincerely,

Casey Rives











Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner

DATE: February 14, 2018

SUBJECT: 6748 Bleight Drive Amendment to Approved Application

APPLICANT INFORMATION:

The applicant, Mrs. Shalvey has previously received an approved Certificate of Appropriateness for a fence located on her property at 6748 Bleight Drive. Since the application was approved by the ARB the HOA has taken up issue with the fence design. The HOA is requesting the homeowners choose a different style fence to meet HOA guidelines and requirements. Mrs. Shalvey will present the details of the issue and the potential solutions at the meeting on February 21, 2018.

The approved application is attached along with email correspondence regarding the need for an amendment. The fence type was a white vinyl fence similar in style to the fencing at Haymarket Station.

STAFF RECOMMENDATION:

The previously approved fence was approved with the idea that the fence would provide a similar look to the fence across the street. There was some discussion about the starkness of the white fence and the style in comparison with the home. Staff recommends the ARB take into consideration the requests of the HOA and help the applicant determine a proper solution.

DRAFT MOTION:

"I make a motion to approve amending Certificate of Appropriateness ZP#2017-027, for the proposed fence at 6748 Bleight Drive. The amended fence design will meet the conditions and requirements set forth by the ARB on February 21, 2018."

Or An alternate motion.

Emily Lockhart

From:

Cathy Shalvey <c-shalvey@comcast.net>

Sent:

Thursday, January 25, 2018 8:26 PM

To:

Emily Lockhart

Subject:

Shalvey 6748 Bleight Drive Fence Proposal

Emily,

It was nice talking to you today. Thank you for taking the time to let me try to explain all this!

Here are notes for the ARB:

To the Town of Haymarket Architectural Review Board:

Hello! We submitted a Proposal for a Fence and a Deck at 6748 Bleight Drive. Thank you for your approval. Simultaneously the same proposal was given to our Villages of Haymarket HOA.

They came back and approved our deck, but rejected the fence. They stated is was "Not Keeping with Community Standards". We read through the HOA docs carefully and thought our proposal did take into consideration a fence that would work with the community. The HOA docs referred to the Town of Haymarket Fence Guides and included Long Fence specifications (attached), but did not state they had to be wood. We also changed the style in our proposal to match Washington Street, as both styles are similar.

After informal conversation with a Board member, they are saying the fence has to be a wooden picket fence of the Long Fence Style attached. They also said the privacy fence would not be allowed, perhaps it's considered stockade, which is not allowed even though our choice was 4 feet with an open top. Their reasoning is a standard is set in the back homes and should not be altered. However, we are Phase 2, different location, different style homes.

We don't think this wood fence it would look nice with our style house OR work well in community. We think it would actually look bad with our style home, and hurt the image coming into town and abutting the park.

They may be open to reconsidering some alterations but we have to adjust our proposal either way. So, we want to clarify a few things with the Town.

Here are some questions for the ARB:

- 1. Is the Long Fence, wooden picket style, in fact the only "officially approved" type of fence that can be used in the Town of Haymarket?
- 2. How did the white vinyl fences along Washington come about, and are they now "officially approved" for homes along Washington Street? If so, can we get that in writing?
- 3. Would the Long Fence Style in white vinyl instead of wood be acceptable to the ARB if the HOA found that acceptable? It is scalloped with a circular finale verses straight with a square finale.

Ideally, our solution would be to switch the style over to the Long Fence style but in white vinyl. We would eliminate the privacy fence altogether and go with a taller, but still open picket style fence, along Washington and, as required, put plantings in front that would provide privacy.

4. Finally, does the ARB have any recommendations considering all these factors? You all know the town and have a good sense of what looks nice. We're open to suggestions to present to our HOA.

If would be nice if we could get recommendations in writing that we could approach the VOH Board with.

Thank you so much for your time and consideration.

A note about the attachments:

- 1. Long Fence Specifications in our HOA from Town of Haymarket Standards
- 2. An idea of a 3 foot white vinyl fence. A 4 foot complimentary fence would go along Washington.


Note: This is not the exact fence, we would have the exact in next proposal but this if for a visual.

Sincerely, Cathy & Tim Shalvey

LONG FENCE

Chantitly, VA 20153-0429 Tel: 703-471-0980 Fax: 703-478-3545 www.longlence.com

CAL RIDGE
HAYMAPKET VILLAGE
GATE DETAIL
T. STANLEY





Cathy Shalvey Shalvey Creative Haymarket, VA 703-673-8378

c-shalvey@comcast.net

Alternate: cathyshalvey1@gmail.com



ZONING PERMIT APPLICATION

ZONING PERMIT #: 2017-07

NOTE: This application must be filled out completely and all components of submission requirements must be met before the application can be accepted and scheduled for review/hearing.

□ Addition

☐Sign (See Spec sheet)

ZONING ACTIVITY: ☑New Construction ☐Alteration/Repair

(Check all that apply	y) UNew Tenant/Use	☐Change of Use	□Relocation	
NAME OF BUSIN	NESS/APPLICANT:	m + Cathy Sha	lucy	
			J. Ft./Length) of Construction	Approx.
SITE ADDRESS:	4748 Bleigh	A Drive	Parcel ID #: 1st	52/7397-09-
Subdivision Nam	ie: Oakvidge V	Mages of Haym	arket Lot Size: . 125	6810
	T:			☐ Yes ☐ No
Special Use Pern	nit Required: 🗆 Yes 🗅	No Homeowners	Association (HOA) Approva	I: ☑ Yes ☐ No
Off-street Parkin	g: Spaces Required: _	S	Spaces Provided:	(in progress)
Add a Fen Necessau Neighbo	y guidelines by Javas. wing Yavas. imentation (attached):	Narrative Plan/Plat		
	FEE: ₩ \$25.	00 Residential 🔲 \$50	0.00 Commercial	
	CERTIFICAT	TE OF APPRO	DPRIATENESS	in 1 - New York (College College Colle
			etc. See Sign Spec Sheet for Si	gnage detail)
	be White Shore			
1. WShorel	ine Talbot Priva	ey 2. 4"Shorelin	e Cil Picket 3. 4	Shoreline Caroli
Supporting Docu	mentation (attached): 🗹	Specification Sheet P	hotograph(s) W/ New E	caps
PERMIT HOLDE	ER INFORMATION	PROPER	HW + TIM Shall	recy
Name		Name	148 Bleight Dri	ve
Address		Address	ymarket, VA.	50/109
City	State Zip	City'	State Zip	due (a)
Phone#	Email	Phone#	Ema	Comcast,

Packet Pg. 45

APPLICANT,	PROPERTY OWN	ER SIGNATU	JRE **	******REQUIRED*****				
foregoing app and as shown and any ada	olication and that the on the attached pla ditional restrictions or the Town Council of the Town Coun	e informatior et, plan and/o and/or con	n provided herein is correct. or specifications will comply ditions prescribed by the applicable laws.	by certify that I have the authority to make the Construction of improvements described herein with the ordinances of the Town of Haymarket Architectural Review Board (ARB), Planning ner Signature				
		***(OFFICE USE ONLY	/** *				
Date Filed:			nt: \$25.00					
			11/02/2017					
□APPROVED	DISAPPROVED	□TABLED	UNTIL:	Deferred until:				
CONDITIONS:			SIGNATURE	PRINT				
DATE TO ARCHITECTURAL REVIEW BOARD (ARB):								
□APPROVED	□DISAPPROVED	☐TABLED	UNTIL:	□DEFERRED UNTIL:				
CONDITIONS:			SIGNATURE	PRINT				
DATE TO TOWN COUNCIL (IF APPLICABLE):								
	ed i stregorijanskog positi i positi i positi i positi i positi i redesirijanskog i 😼			□DEFERRED UNTIL:				
TOWN COUNC	IL (where required):		SIGNATURE	PRINT				
CONDITIONS:			SIGNATURE	(10)47				
<u> </u>								

Fence Proposal

6748 Bleight Drive, Haymarket VA

Tim & Cathy Shalvey
508-479-6669 | 703-673-8378
<u>t.shalvey@comcast.net</u>
<u>c-shalvey@comcast.net</u>

OVERVIEW

The proposed fence would surround the back yard on or near the property line to provide privacy and safety for young children and pets. The type of fence is the exact same fencing that is across the street so it will conform to neighborhood appearance.

The side of the fence, parallel to Washington Street, would come off the back of the house approximately 2' and run parallel with Washington on the line even with the front porch. This will provide an inset in front of 3 windows for a bed and landscaping. This fence will be a 6' tall, white, privacy fence and there will be a matching 4' wide gate.

The back fence will be 4' tall, white picket fence, the exact same as across the street. It will provide safety and some privacy but allow views from the house to the park and will not provide an open appearance from the park looking in.

The right side will run on the property line between us and the next neighbor on Bleight Drive and will wrap around in back of the driveway and align with the back of the house. This will be the 6' tall Privacy fence and will have a 5" gate to allow landscaping equipment in.

There will be a small utility surround attached to the house that abuts the fence near the driveway. This will be 4' tall solid fence, it's the exact same as the 6' fence but does not include the open top part so it will blend well in view from Bleight Drive. The front of this enclosure will all be an 8' double gate.

Contractor will obtain Building Permit and manage Inspection.

SIZE:

Total Linear Feet: 339 feet

MATERIALS & LENGTH:

Side that runs parallel with Washington Street: Shoreline White Vinyl 6' Talbot Privacy Fencing approximately 24' long with (1) 4' wide Single Gate

Back that runs along Haymarket Park:

Shoreline White Vinyl 4' Cecil Picket Fencing approximately 74' long

Side between houses and behind driveway facing Bleight Drive:

Shoreline White Vinyl 6' Talbot Privacy Fencing approximately 40' long with (1) 5' wide Single Gate

Utility Surround:

Shoreline White Vinyl 4' Caroline Privacy Fencing approximately 3' long with (1) 8' wide Double Gate

AC Surround

Shoreline White Vinyl 4' Caroline Privacy Fencing approximately 3' on 2 sides to allow access on one side

Other Material Notes:

- All fencing will be finished with New England style, white vinyl caps.
- All posts are 5" x 5".
- All posts to be set in concrete into ground 24" 36" each section is inserted to each post and latched in place.
- No screws or nails are used.
- All gates to have self closing black hinges and two way lockable latches.

ATTACHED:


- House plat showing outline of fence
- · Drawing of fence
- Photos and Diagrams of Fencing Materials
- · Photos of yard, back of house
- Photos of properties across the street with same fence
- HOA request is submitted and in progress
- Business Proposal and License


WASHINGTON STREET



HAYMARKET COMMUNITY PARK

Packet Pg. 49






Talbot




6' White Talbot Privacy Fence will be on sides and behind driveway.



Cecil



4' White Cecil Picket Fence will along back of property.



Caroline

4' White Caroline Fence is the exact same as Talbot without the top. Will be on one side of Utility Surround facing Bleight Drive and on 2 sides of AC surround.





To the left are photos of the homes/ community directly across the street.

It shows the 6' Talbot privacy fencing abutting the 4' Cecil picket fencing.

The photos below show more of the 4' Cecil fencing and a gate with hardware.

The New England caps will also be the same.

Note that this is all white fencing against cream trim in the homes.













Estimate



Beitzell Fence Co 4665 Sudley Road Catharpin, VA 20143 (703)754-0011

www.beitzellfence.com

ADDRESS

Cathy Shalvey 6748 Bleight Dr. Haymarket, VA

ESTIMATE#

DATE

8372

10/09/2017

SALES REP

Patrick Beitzell

ACTIVITY AMOUNT Furnish and install approx. 78' of 6' high Shoreline #Talbot, white vinyl privacy 7.900.00 fence. (Front and sides) Furnish and install (1) 4' wide single gate and (1) 5' wide single gate. Furnish and install approx. 15' of 4' high Shoreline #Caroline, white vinyl privacy fence. (Trash enclosure / ac unit) Furnish and install (1) 8' wide double gate. Furnish and install approx. 80' of 4' high Shoreline #Cecil, white picket fence. (Back line) All posts to be set in concrete and finished with New England style, white vinyl All gates to have self closing hinges and two way lockable latches. Posts- 5"x5", Gate posts- 5"x5" with aluminum inserts. Advertising discount. -125.00Buyer to provide engineering, control points for elevation, horizontal and

vertical alignment, determination of property lines, access to work area, clearing, restoration of finished grade, re-seeding, on-site disposal area of spoils, core drilling, and setting of inserts. Location of underground utilities or obstructions that are not identified through the local on-call service are to be marked by buyer. Seller is held harmless and indemnified against claims resulting from damages to unidentified utilities. The work will be performed in compliance with industry standards and guaranteed against defects in materials and workmanship for one year. This contract embodies the entire understanding between the parties. There are no verbal agreements or representations in connection therewith. Estimate good for 30 days. Any alterations from the above specifications or estimated quantities involving additional costs is extra to the contract.

TOTAL

\$7,775.00

Accepted By

Accepted Date

COMMONWEALTH of VIRGINIA

EXPIRES ON 03-31-2019

Department of Professional and Occupational Regulation 9960 Mayland Drive, Suite 400, Richmond, VA 23233 Telephone: (804) 367-8500

NUMBER 2705061599

BOARD FOR CONTRACTORS CLASS A CONTRACTOR *CLASSIFICATIONS* CIC HIC



BEITZELL CONSTRUCTION INC BEITZELL FENCE CO 4665 SUDLEY RD CATHARPIN, VA 20143



DPOR-LIC (05// (DETACH)

Status can be verified at http://www.dpor.virginia.gov

(SEE REVERSE SIDE FOR PRIVILEGES AND INSTRUCTIONS)

COMMONWEALTH of VIRGINIA Department of Professional and Occupational Regulation

CLASS A BOARD FOR CONTRACTORS CONTRACTOR

CLASSIFICATIONS CIC HIC NUMBER: 2705061599 EXPIRES: 03-31-2019

BEITZELL CONSTRUCTION INC BEITZELL FENCE CO 4665 SUDLEY RD CATHARPIN, VA 20143 3-31-2019

Status can be verified at http://www.dpor.virginia.gov

DPOR-FC (05/2015)



Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner

DATE: February 14, 2018

SUBJECT: Haymarket Baptist Church, Fence Application Amendment

APPLICANT INFORMATION:

The applicant, Haymarket Baptist Church is in the process of finishing all site work. The fencing company has informed the applicant that the previously approved fence will not fit in that location due to narrow spacing, see below for more detail. In order to complete the site plan the applicant is coming to the ARB to discuss the necessary changes that need to occur and the solutions.

Email correspondence with Dan Sawyer-- "The reason the "board on board" fencing cannot be installed, as per plan, down the playground side is due the existing chain link fence. In addition, the current chain link fence down the playground side is too close to the property line which prohibits the fence company to work on both sides to achieve the "board on board" fence. So, the solution from the fencing company is to install a "tight fit" single sided privacy fence where the boards are installed tight together on the outside. I've attached a photo of the proposed "tight fit" fencing in lieu of the "board on board".

And I will be present at the meeting with a copy of our plans and example of the single sided "tight fit" fencing that we are proposing."



STAFF RECOMMENDATION:

The proposed fence will be installed so that the backside (what you see above) will be seen from the parking lot. The ARB needs to consider how this fence will look in the parking lot and along the side of Haymarket Baptist. The proposed solution will meet the requirements for the fence as set forth in the site plan.

DRAFT MOTION:

"I make a motion to approve the amended fence for Haymarket Baptist Church located at 14800 Washington Street. The fence will follow all conditions set forth by the ARB February 21, 2018.

Or An alternate motion.



Town of Haymarket 15000 Washington Street, #100 Haymarket, VA 20169 703-753-2600

Emily Lockhart TOWN PLANNER

MEMORANDUM

TO: Architectural Review Board FROM: Emily Lockhart, Town Planner DATE: Updated: February 14, 2018

SUBJECT: Zoning Permit #2017-029, 6810 Jefferson Street, Residential Demolition Application

UPDATED INFORMATION:

At the last Architectural Review Board Meeting the Board tabled Zoning Permit #2017-029 until further information regarding the structural integrity of the home could be submitted. On January 20, 2018 the ARB and Town Staff toured the structure and property located at 6810 Jefferson Street. At this tour the Board and Staff were able to see for themselves the condition of the home (interior and exterior) and get a better sense of the property. No determinations, comments or recommendations were made at this meeting between the applicant, the Board and Staff.

In response to the Board's request for a structural engineer's report, the applicant submitted the report on February 9, 2018. The structural analysis was completed by Tom Basham, PE. The concluding remarks from Mr. Basham are as follows;

"As a result of the foregoing observations I hereby conclude this dwelling is not structurally sound. There are significant failures in all structural elements of the building including the foundation, floors, walls and roof. These deficiencies are prevalent over more than 50% of the building. They appear to be the product of time, poor and outdated construction techniques, lack of maintenance, and water and insect damage.

It is my professional opinion that the structural deficiencies with this building are so drastic that the building is a total loss and should be demolished."

Please review the attached structural evaluation that Mr. Basham has submitted. The evaluation will give a more detailed account of the observations and findings. In addition to the evaluation provided I have reached out to Mr. Basham to better understand the possibilities for replacing the foundation or relocating the structure. Please see the attached email correspondence with Mr. Basham.

In addition to the structural engineer's report Mr. Cowne, the interested buyer, has submitted basic concept plans for the two properties. He intends to build two homes similar in style to those along Jefferson Street. The concept plan and image are attached.

Lastly, at the January meeting it was brought to the Town's attention that 6810 Jefferson Street was recorded as two parcels rather than one. Upon further investigation and review by the Town Attorney it has been determined that the structure is located at 6810 Jefferson Street and a second parcel is located beside it at 6812 Jefferson Street.

STAFF RECOMMENDATION:

The home which was built in approximately 1901, currently requires major repairs for individuals to safely occupy the space. The owners of the property do not wish to make this investment and are ready to sell the property. The home is considered a historic structure within the Town and is listed on the Historic Building Inventory list in the Comprehensive Plan. The Architectural Review Board needs to consider the feasibility of maintaining this property and the financial investment it will require to bring it back up to livable standards.

The applicants have submitted the following items for the demolition application upon the request of the ARB and Staff.

- Demolition permit application
- Narrative stating the reasoning for request
- Tax records of the property
- Building Inspection Report
- Structural Engineer's Report
- General concept plans for the property if a demolition permit were to be approved
- A tour of the home

While the home is a historic structure Staff feels that the financial investment is greater than one might be willing to invest in the property. However, the home has been boarded up and unoccupied for over 30 years. The lack of maintenance and care for the property overtime is very evident. The lack of maintenance has deteriorated the home so badly that the only feasible option is to apply for a demolition permit. This reality is disappointing for the Town since we consider the home to be a contributing historic structure. While some have questioned the historic value, the Town feels that the home is representative of our earlier formative years and the architectural style of the early 1900's. Allowing historic structures to be demolished within Town sets a precedence for all remaining historic structures. The ARB should consider all documents before them and make a decision based on the facts presented.

With this being said, Staff and the ARB must face the reality of the situation. It has been determined the home is not structurally sound and that the structural deficiencies are so drastic that the building is a total loss. With this being said, there is an interested buyer who wishes to develop two homes on the parcels similar in style to the surrounding homes on Jefferson and Fayette Street. The potential new home(s) would enhance the property.

Staff feels that the applicant has done their due diligence in providing everything the Board and Staff requested. The documents show that the structure is not structurally sound and the financial investment to restore may be greater than anyone is willing to invest. While the situation is unfortunate for the Town, Staff recommends the ARB to approve the demolition application with the recommendation (or condition) to hire a

professional photographer to document the property and its historic elements. In addition to hiring a photographer Staff recommends the ARB approve the permit with the condition that the demolition may occur only following receipt of a building permit for the new construction.

DRAFT MOTION:

"I make a motion to approve Certificate of Appropriateness ZP#2017-029, to demolish the residential home at 6810 Jefferson Street with the following conditions: 1) the owner hire a professional photographer to document the home in accordance with the Historic Guidelines and 2) the demolition may occur only following receipt of a building permit for the new construction."

Or An alternate motion.



30 January 2018

Page 1 of 6

Patrick Cowne 4713 Benjamin Cross Ct. Chantilly, Va. 22151

SUBJECT: Structural Evaluation - # 6810 Jefferson St, Haymarket, Va.

Dear Sir;

As you know, today I made a visit to the subject site to conduct an evaluation of existing dwelling. I had the opportunity to review the Home Inspection Report by John Murray prior to my site visit. As a result of this site visit, inspection and evaluation I made the following observations:

OBSERVATIONS

- 1. The structure is a two story single family dwelling constructed at least 70 years ago, and quite possibly much older.
- 2. The dwelling is a balloon framed building on a masonry foundation with clapboard wood siding and metal roof.
- 3. From the outside of the building it appears the masonry foundation is failing and in the process of disintegrating. The brick has severe cracks and is clearly moving laterally and vertically. See Photo # 1 & 2
- 4. From the outside of the building it appears a significant portion of the building has wood frame elements in contact with the ground. This lack of vertical separation from the wood structural elements and the ground have clearly allowed for water damage and insect infestation. See Photo # 3 & 4
- 5. From the inside of the building it is evident the floors are uneven and show considerable settling and weakness in several locations.
- 6. The floor joists for the first floor are connected to the outer rim board by notching, which has not held up well over time, due to settlement in the foundation, cracks in the joists, insect damage and decay from rotting.
- 7. The wallboard had been torn away in numerous locations to display wall, ceiling and second floor framing components. In every one of these locations the structural members have been severely compromised by either rot or insect damage.



Page 2 of 6

- 8. The roof on the second floor and the shed roof attached to the dwelling over the first floor have been compromised for decades and water damage from this defect is extensive.
- 9. The rafters for the house have been cut for the "birds mouth" to sit on the top wall plate in such a way as to significantly reduce the structural width of the rafter. This is further exacerbated by the rafters being undersized for current loading conditions.
- 10. The crawl space under the framed first floor varies from 0" to about 8". This exposes to structural timbers to excessive moisture and insect damage.

CONCLUSIONS

As a result of the foregoing observations I hereby conclude this dwelling is not structurally sound. There are significant failures in all structural elements of the building including the foundation, floors, walls and roof. These deficiencies are prevalent over more than 50% of the building. They appear to be the product of time, poor and outdated construction techniques, lack of maintenance, and water and insect damage.

It is my professional opinion that the structural deficiencies with this building are so drastic that the building is a total loss and should be demolished.

If you have questions please let feel free to contact me. I may be reached at 703-594-2425 ext 105, or by e-mail at tom@nokesvilledesign.com.

Sincerely;

D. Thomas Basham PE

20182

Page 3 of 6



PHOTO # 1: Foundation Deterioration

Page 4 of 6



PHOTO # 2: Foundation Failure and Deterioration

Page 5 of 6



PHOTO # 3: Wood Framing in Contact With Soil

Page 6 of 6



PHOTO # 4: Wood Framing in Contact With Soil

Emily Lockhart

From: Sent: Tom <tom@nokesvilledesign.com> Tuesday, February 13, 2018 6:05 PM

To:

Emily Lockhart

Subject:

Re: 6810 Jefferson Street

Emily -

Please see below my answers to your questions:

- 1. Due to the decay in the rim boards/beams and joists in the floor, I do not think there is stable enough base in the dwelling to apply pressure vertically to lift the structure. Over half of the building is actually in the ground now and the rest of it has about a 6" crawl space. All of this has allowed significant decay of the structural elements in the floor system.
- 2. As I have stated above, the lower portion of this building is the most deficient structurally, so lifting it and placing it on a trailer to move elsewhere would not go well. It would be like picking up a cardboard box that had been setting in water the bottom would fall out. I have personally raised two 100 year old buildings and repaired the joists and foundation, so I do know what is possible. In this case, because of the decay and the way the joists were notched into the band beam, I do not think the house is stable enough to raise or move.

Please let me know if you have any follow up or additional questions. If I have not adequately addressed your questions please let me know.

Tom Basham PE

From: Emily Lockhart <elockhart@townofhaymarket.org>

Sent: Tuesday, February 13, 2018 2:18:29 PM

To: Tom

Subject: 6810 Jefferson Street

Good Afternoon Mr. Basham,

I am reaching out to you regarding the structural evaluation of 6810 Jefferson Street. In preparation for the next Architectural Review Board meeting I was hoping to get a few questions answered. The questions below have been brought up previously when discussing the property. All insight or information you can give regarding these options would be much appreciated.

- Is the structure stable enough to jack it up and replace the foundation?
- Is the structure stable enough to relocate the structure elsewhere?


Thank you very much,
Emily Lockhart
Town Planner
Town of Haymarket
15000 Washington Street, Suite 100
Haymarket, VA 20169


Phone: 703-753-2600

Email: <u>elockhart@townofhaymarket.org</u>
Website: <u>www.townofhaymarket.org</u>









CONCEPT PLAN

JEFFERSON STREET

GAINESVILLE MAGISTERIAL DISTRICT

PRINCE WILLIAM COUNTY, VIRGINIA

DATE: 7 FEBRUARY 2018 SCALE: 1"=20'





Ms. Emily Lockhart, Town Planner Town of Haymarket 15000 Washington St. Haymarket, VA 20169

RE: 6810 Jefferson Street Update

Dear Ms Lockhart,

Upon your recommendation this letter is to confirm my conversation with you pertaining to the withdrawal of the purchase agreement by the prospective purchasers. They decided that the size of the lot was not going to work for the home and lifestyle they wanted to pursue. We have, therefore, put the lot back on the active market for sale and have already received a few inquiries. We are marketing it to clients who intend to build a home similar to house already existing on Jefferson St and Fayette St.

As soon as we have received an additional purchaser for the property, we will be sure to let you know immediately.

I would still welcome the opportunity to preview the property with you and members of the ARB to provide a first-hand review of the condition of the property.

Sincerely,

Danny L. Radtke, ABR, CRS, GRI, CDPE Associate Broker

RE/MAX Gateway Cell: 703-283-9540 7521 Virginia Oaks Drive Tel: 571-261-3963



RE/MAX Gateway November 9, 2017

Ms. Emily Lockhart, Town Planner Town of Haymarket 15000 Washington St. Haymarket, VA 20169

RE: 6810 Jefferson Street

Dear Ms Lockhart,

Upon your recommendation we have solicited the inspection of the property by a certified home inspector to determine the current condition of the property and the ability to restore the aged home. That report is included with this re-application for demolition approval including multiple pictures showing the status of the structure.

As to historical value of the property, research has only documented ownership of the property to approximately 1900 and since that time it has been owned as a personal residence. The family first acquired the property in 1953 and was then conveyed to relatives in 1982 who are the current owners. The building has not been lived in since that date and consequently has experienced deterioration. There is no ability or intention of the owners to expend any efforts or money to do any restoration of the building.

The family has now decided it is time to dispose of the property and in order to do so, are willing to sell the land with the idea that the existing building has no restorable potential and the value is only in the land value. A purchaser has been identified and a purchase agreement executed with the intent to build a new home on the property. The intent is to build a home of similar style, size and construction materials as those in the adjoining area. This agreement is contingent on getting confirmation from the Town of Haymarket that this would be permitted. Once this commitment is granted, the contract will be consummated and a demolition permit and construction permit will be submitted for the Town's approval.

I would welcome the opportunity to preview the property with you and members of the ARB to provide a first-hand review of the condition of the property.

Sincerely,

Danny L. Radtke, ABR, CRS, GRI, CDPE Associate Broker

RE/MAX Gateway Cell: 703-283-9540 7521 Virginia Oaks Drive Tel: 571-261-3963 Gainesville, VA 20155 Fax: 703-483-3545

Packet Pg. 74



LICA

ZONING PERMIT APPLICATION

ZONING PERMIT #: 2 P 2 0 17 - 029

NOTE: This appli	cation must be filled out completely an before the application can be accept	ed all components of	of submission requirements must be met for review/heuring.
	□ New Construction □ New Tenant/Use □ Change of		
NAME OF BUSINES	S/APPLICANT:		
PROPOSED USE:	Residential	_ Size (Sq. Ft./Le	ngth) of Construction:
SITE ADDRESS: _	6810 Jefferson Si	<u> </u>	Parcel ID #:
Subdivision Name:			Lot Size:
ZONING DISTRICT:			Site Plan Required: Yes No
Special Use Permit I	Required: 🗖 Yes 🛱 No 💮 Hoi	meowners Associ	ation (HOA) Approval: 🗖 Yes 🞾 No
	Spaces Required:		
BRIEF DESCRIPTION	OF ACTIVITY: (i.e. previous use, heig	ht/length of fencin	g,deck, specs, etc.)
Kegiifst	ing approval to	o denjoli	sh and remove
existilly	beniding on pi	operly	
Supporting Docume	ntation (attached): 🕱 Narrative 🗖 F	Plan/Plat 🛭 Speci	fication Sheet
	FEE: 🗓 \$25.00 Residenti		
ADDITIONAL DESCR	CERTIFICATE OF A IPTION: (i.e. color, type of material, f		
ADD I COM	ntation ($attached$): \square Specification S	heet 🖵 Photogra	aph(s)
PERMIT HOLDER H	FORMATION	PROPERTY OW	NER INFORMATION
Janny K	adthe	Dollie He	Inkinson & IR Leonard
1521 Mira	MI GORG DE	Name (9)	Day Lord 14
Address	1 111	Address	Day Fee G
MINESVIlle	0 V4 ZO155	Spring Fi	eld VA 22152
703-283-954	State Zip (D) Nanta Hhe Llaamid	703-51	State Zip 69-7824
Phone#	Email Email	Phone# dnah	ank 2@ Evison, net

APPLICANT / PROPERTY OWNE	R SIGNATURE	*****REQUIRED*****
l, as owner or authorized agent for foregoing application and that the and as shown on the attached plan	r the above-referenced point information provided her information provided her information and/or conditions prescribed all other applicable law	arcel, do hereby certify that I have the authority to make the ein is correct. Construction of improvements described herein as will comply with the ordinances of the Town of Haymarket libed by the Architectural Review Board (ARR). Planning
	OFFICE U	SE ONLY
Date Filed: 1 22 2017	Fee Amount: \$20	00.00 Date Paid: 11/22/2017
DATE TO ZONING ADMINIS		
□APPROVED □DISAPPROVED	TABLED UNTIL:	DEFERRED UNTIL:
CONDITIONS:	SIGNATURE	PRINT
DATE TO ARCHITECTURAL R	EVIEW BOARD (ARE	3);
□APPROVED □DISAPPROVED	TABLED UNTIL:	Deferred until:
CONDITIONS:	SIGNATURE	PRINT
DATE TO TOWN COUNCIL (II	F APPLICABLE):	
□APPROVED □DISAPPROVED	TABLED UNTIL:	ODEFERRED UNTIL:
TOWN COUNCIL (where required):		
CONDITIONS:	SIGNATURE	PRINT

CERTIFICATE/LETTER OF QUALIFICATION COMMONWEALTH OF VIRGINIA VA CODE SI 62-893, 62-1101, 62-1105, 62-1107, 642-805, 643-807

Court File No. W-16143

Prince William County Circuit Court

I, the duly qualified deputy clerk of this Court, CERTIFY that on February 16, 2017

Scott H. Donovan Esq.

duly qualified in this court, under applicable provisions of law, as Administrator, c.t.a of the estate of

Jean Rosamond Leonard

R DECEASED COMINGE CONCREDED

The powers of the fiduciary(ies) named above continue in full force and effect.

\$225,000.00 bond has been posted.

Given under my hand and the seal of this Court on

June 5, 2017



0937457 COMMONWEALTH OF VIRGINIA

COMMONWEALTH OF VERGENA - CERTIFICATE OF DEATH DEATHWAY OF THE OF DEATH

	The first of the f
302.	RASAMAN LEONGINA MANAGEMENT
110	The state of the s
ACM PACKET	1 and of Controlled Co
	Age Locate Department of the control
a Cheller	-
9 10	ce a de destructues estas de la constante de l
Marine San Comment	N METHODORIES N METHODORIES ET WIND OF DEP IT PARKS OF DEP
	Stonewall Me
351	Street L. Mers S679 Carter St. Managang, VA 2010 Sneeden name of the Science of t
	Marie Marie Marie Marie Marie Marie Marie Control Fortuna
Mary and a series	POT the second rather in the party of the
ACCOUNTY OF THE PROPERTY OF TH	
William St.	Decient Total Tests Staked Red Lewis Little 2022 22
20.76	

FORM CC-1625 MASTER 10/12

Phone #:

Grid:

Parcel:

City Tax:

Plat Folio:

Refuse: 70.00

Improvement

Mult. Class:

\$23,100

\$22,500

\$22,500

Deed Folio: 1,433

Condo/Coop Project:

Company Owner:

Block/Square:

Addl Parcel Flag/#:

Homestd/Exempt Status:

Care of Name:

County: PRINCE WILLIAM

Full Tax Record

07-Sep-2017 4:09 pm

Absent Owner Yesional Inform

Tax Map:

Sub-Parcel:

Tax Rate: 1.12

Plat Liber:

Map: 7297-88-5078

Tax Levy Year: 2,016

DOLLIE HANKINSON , JR LEONAR

Property Address: 6810 JEFFERSON ST, HAYMARKET, VA 20169-

Lot:

Legal Subdiv/Neighborhood: HAYMARKET TOWN PLAT Incorporated City: HAYMARKET TOWNYES IONAL IN

Owner Name: DOLLIE HANKINSON

Addtnl: J R LEONARD T-C

MAILING ADDRESS: PO BOX 24, , VA 20156 0024

LEGAL DESCRIPTION: 1 L

Mag/Dist #: 13

Tax ID: 44064

Election District: Section:

Map Suffix: Historic ID:

Tax Year 2016

State/County Tax: 1,130.98

Spec Tax Assmt: 73.58

Front Foot Fee:

Total Tax Bill: 1,312.76

Exempt Class: Tax Class:

Legal Unit #:

Subdiv(Ph:

Suffix:

Agri Dist:

Total Tax Value Year Assessed 2017 \$101,400

2016 2015

DEED Transfer Date

PROPERTY DESCRIPTION

Land Use Code: Residential

Prop Use: SFD DETACHED

Price 01-Jun-1982

Zoning Desc: SUBURBAN RESIDENTIAL (4/A

Section 1

\$100,800 \$100,800

\$15,000

Deed Liber: 1,180

Land

\$78,300

\$78,300

\$78,300

Grantor

Zoning Code: R4

Square Feet: 26,062.00 Plat Liber/Folio: / Quality Grade: LOW Xfer Devel.Right:

Site Influence:

Section 2

Roofing:

Style:

Units:

Building Use:

Sq Ft:

Sq Ft:

Sq Ft:

Lot Description:

Year Built: 1.901

Property Class: 11

Irregular Lot:

Section 3

Pavement: Section 4

Land Use

Grantee

Census Trct/Blck: /

Property Card: 1.00

Road Description:

Road Frontage:

Topography:

of Dormers:

Fireplaces:

Garage Type:

Garage Const.:

Garage Spaces:

Garage Sq Ft:

Year Remodeled:

Model/Unit Type:

Sidewalk:

Acreage: 0.60

\$0

\$0

\$0

Section 5

Base Sq Ft: 1,240

Sq Ft: 96

Sq Ft:

Story Type: Description: Dimensions:

Construction:

Area: Foundation:

Ext Wall: Stories: 1

Total Building Area: Patio/Deck Type:

Balcony Type: Attic Type: Rooms: 5

Bedrooms: 2 Full Baths: 1 Half Baths: Baths:

Other Rooms: Other Amenities: Appliances:

Gas: Electric:

10

Courtesy of: Dan Radtke Home: (703) 283-9540

Office: (571) 261-3959 Cell: (703) 283-9540 Email: dan@vafreedomteam.com Company: RE/MAX Gateway

Office: (703) 754-1770 Fax: (703) 753-1786 Fireplace Type:

Bsmt Type: Bsmt Tot Sq Ft: Bsmt Fin Sq Ft:

Bsmt Unfin Sq Ft:

Heat: Other Water:

Outbuildingspliance Sewer: 3as Underground: 110

Air ConditioningRo

Interior Floorier Ame

Living Area:1,240

Pool Type:

Roof Type:

Porch Type: Screened/Enclose

talf Balls

Baths

Fuel: Walls:

Tax Record Updated: 8/23/2017 10:54:18PM

Lot & Land Synopsis - Agent




Tax Record

Neighbor Photos

Metropolitan Regional Information Systems, Inc.

PW10018585 - PRINCE WILLIAM 6810 JEFFERSON ST HAYMARKET VA, 20169 Synopsis Lot-Land **Agent Synopsis** Lot-Land





© 2017 Microsoft Corporation
© 2017 HERE l> bing

Ownership: Fee Simple, Sale

Leg Subdivision: HAYMARKET TOWN PLAT

Adv Subdivision: None

Project Name: Tax ID: 44064 Lot/BlockOr Square: /

Elementary School: HAYMARKET

Status: ACTIVE Auction: No

Road Frontage: 75

Total Taxes: \$1,370

List Price: \$214,997 Transaction Type: Standard

ADC Map Coord: GPS Area:

HOA Fee: Tax Year: 2015

Building Sites:

Folio:

Di.

Middle School: RONALD WILSON RHigh School: BATTLEFIELD

PROPERTY INFORMATION:

Lot AC/SF: .598 / 26062

View/Exp: Soil:

Exterior Features:

Lot Description: Partly Wooded

Topography: Sloped Present Use: Residential

Special Permits:

Building Permits: No Building Permits Development Status: Utilities at Site Disclosures: Exempt - Disclosure/Disclaimer

HOA Fee Includes:

UTILITIES:

Heat Fuel: None Cool Fuel: None Water: Public

Sewer/Septic: Public Sewer

Remarks: This Original 26000 Sf Lot Has Been Offficially Subdivided And Recorded Into Two Building Lots On The Corner Of Fayette And Jefferson Streets. Gental Slope Toward Jefferson St. Town Planner Indicates Building Not Of Historical Value. One Sewer Tap Has Been Paid.

Show Instructions: Show Anytime, Sign on Property, Vacant

Directions: I66 West, Rt 15 South, Rt55 East To A Right On Jefferson St. Property On Right Just Before Railroad Tracks. Look For Sign On The Right

Orig List Price: \$214,997

DOM-MLS: 40

BROKER CONTACT:

Listing Company: RE/MAX Gateway Listing Agent: Dan Radtke Agt Office: (571) 261-3959 Owners: Hankinson

Showing Contact: Dual Agency: Yes Var Comm: No

Update Date: 29-Jul-2017

DOM-Prop: 40

Second Sewer Tap Fee Is \$10,800. Each Water Tap Is \$5,010. Both Lots Must Be Purchased At The Same Time.

Home: (703) 283-9540 Pager: (703) 283-9540

Home:

Des Rep: Yes Add'l:

List Date: 29-Jul-2017 **Update Type: MEDIA**

Broker Code: RMAX151 Brkr Office: (703) 754-1770

Cell: (703) 283-9540 On-Site:

Buy Comp: 3% SubComp: 0

me:

ger: (703)













NAMANSE NA KELLOM IAJO NVOTO TESTO NASO

CHICHARD S



1/84















Prepared for Exclusive Use by:

Ms. Dollie Hankinson

Address of Property:

6810 Jefferson St Haymarket VA 20169

Date of Service:

10/11/2017



Company Providing Service:

John Murray 3380000859

Rayner Lea, LLC dba HouseMaster of Bull Run 11106 Bristow Road Bristow, Virginia 20136 571.393.3311

==<u>EXPRESS</u>. R

Report ID: 1710117 / Hankinson

SUMMARY OF INSPECTOR COMMENTS

This Summary of Inspector Comments is only one section of the Inspection Report and is provided for guidance purposes only. This Summary is **NOT A HOME INSPECTION REPORT** and does not include information on all conditions or concerns associated with this home or property. **The Inspection Report** includes more detailed information on element ratings/conditions and associated information and **must be read and considered in its entirety prior to making any conclusive purchase decisions or taking any other action**. Any questionable issues should be discussed with the Inspector and/or Inspection Company.

Note: While listings in this Summary of Inspector Comments may serve as a guide to help prioritize remedial needs, the final decision regarding any action to be taken must be made by the client following consultation with the appropriate specialists or contractors. Cost figures provided in this summary are to help prioritize the findings. Any cost provided is an approximate range and should not be considered an accurate estimate. Cost among qualified contractors can vary greatly. Any item with a significant cost figure provided shoul be evaluated by licensed, qualified contractor or specialist, and repaired accordingly.

1. ROOFING

1.0 ROOFING

Poor/Defective

Built-Up roofs by their design do not allow for visual evaluation of the water tight membrane. These roofs require special maintenance in order to remain leak free and the life expectancy varies with the quality of materials used. Therefore, no rating can be given to the roof and no evaluation was performed. Have further evaluated as desired.

1.1 ROOFING #2

Poor/Defective

Aging metal roofing noted. This material can have a lengthy service life, but requires periodic re-coating and maintenance. Have evaluated and serviced every 3-5 years by a qualified metal roofer.

1.2 **ROOFING #3**

Poor/Defective

Aging tin roofing noted. Tin can have a lengthy service life, but requires periodic re-coating and maintenance. Have evaluated and serviced every 3-5 years by a qualified metal roofer.

1.3 CHIMNEY / VENT(s)

Poor/Defective

Cracks in crown (mortar cap) noted, seal and maintain or replace as required. (Crowns typically require replacement every 10-15 yrs.)

The crown (mortar cap) of the chimney is worn. Monitor and anticipate replacement needs. (Crowns typically require replacement every 10-15 yrs.)

Mortar deterioration noted. Monitor or correct as desired.

Defective (improperly installed) flashing noted at the chimney; reseal and maintain or replace as required. Initial roof leaks and/or recurring roof leakage problems are often due to inadequate or damaged flashing. All flashings should be checked periodically or if leakage occurs. Repair or seal as needed.

1.6 FASCIA / SOFFITS

Poor/Defective

Decay and presence of Wood Destroying Insects noted to fascias at front, rear and sides of house, correct as required.

Deteriorated paint noted, maintenance required.

2. EXTERIOR ELEMENTS

2.0 SIDING / WALL CLADDING

Poor/Defective

Surfaces on older homes may have layers of lead-based paint, particularly pre-1978 paint applications. The likelihood of exposure to lead hazards is minimal if the paint is intact or covered with another product. Neither testing nor assessment is part of a standard home inspection. Testing by a qualified specialist should be arranged if paint damage or other potential hazards exist or to address individual concerns. Paint is deteriorated; maintain as required.

Siding has several holes from damage and prior renovations.

2.1 WINDOWS

Poor/Defective

All windows are boarded up and rotting around the sills.

2.2 ENTRY DOORS

Poor/Defective

Moisture damage noted to jamb/frame at Front Entry, correct as required. Any damage should be corrected/addressed properly to minimize consequential damage or further infestation.

2.3 STAIRS / STOOPS

Poor/Defective

Deteriorated stoop noted at Front Entry; repair/replace as required.

No handrail at the stoop at the Front Entry; recommend adding for safety.

2.5 FOUNDATION SURFACE

Poor/Defective

Deteriorated bricks and mortar noted in curtain/veneer wall at front, rear and sides of house, have area re-pointed by a qualified brick mason.

2.6 ELECTRICAL / GFCI

Poor/Defective

Power was not available to the house; romex wiring is aged, no outside Outlets installed, lighting wires/bulbs are bare. Replace wiring and install Fixtures.

3. SITE ELEMENTS

3.3 GROUND SLOPE AT FOUNDATION

Poor/Defective

Negative grade noted at front, rear and sides of house; correct as required to help reduce water penetration and potential settlement concerns.

3.4 SITE GRADING

Poor/Defective

Grading slopes towards the house at front, rear and sides of house; monitor runoff and correct as needed.

4. INTERIOR ELEMENTS

4.0 CEILINGS / STRUCTURE

Poor/Defective

Water damage noted at Upstairs Bedroom; repair as required.

Hole in ceiling noted at Upstairs Bedroom, repair as required.

There is a potential that exterior and/or interior surfaces are covered with a lead-based paint, particularly in pre-1978 homes. It paint is intact or covered with another product the likelihood of the release of any significant lead is minimized. No lead-based paint assessment is made as part of a standard home inspection. Individual concerns should be considered and testing by a qualified specialist can be arranged if needed.

4.1 WALLS / STRUCTURE

Poor/Defective

Evidence of many prior repairs noted. There is a potential that exterior and/or interior surfaces are covered with a lead-based paint, particularly in pre-1978 homes. If paint is intact or covered with another product the likelihood of the release of any significant lead is minimized. No lead-based paint assessment is made as part of a standard home inspection. Individual concerns should be considered and testing by a qualified specialist can be arranged if needed.

See Ceilings note above.

4.2 FLOORS (FRAMED)

Poor/Defective

Damaged flooring; repair as required.

4.3 STAIRS/STEPS

Fair

No handrail noted; add for safety.

Low headroom noted at stairway entry. Exercise caution.

4.4 RAILINGS

Poor/Defective

No handrail noted at second story stairs; add for safety.

4.5 WINDOWS

Poor/Defective

Defective retention springs/ballast weights noted at , Kitchen Living Room Guest Bed Room Small Bed Room. Correct as required.

Cracked panes noted at Kitchen Living Room Guest Bed Room Small Bed Room; replace as required.

General maintenance needed.

Older single glaze windows noted. Glazing and other maintenance required.

4.6 ROOM DOORS

Poor/Defective

Older and missing doors, anticipate maintenance and adjustment needs.

5. FOUNDATION / SUBSTRUCTURE

5.0 FOUNDATION / SUBSTRUCTURE

Poor/Defective

A condition known as spalling was noted in the bricks of the foundation walls. Spalling is the slow deterioration of brick, reducing them to a sandy powder, as the effects of time, moisture, and other factors take their toll. This deterioration can be slowed, and effected walls stabilized by applying a surface "parge" coat of concrete to the walls. Recommend coating walls to control spalling and maintain structural integrity of foundation.

The potential for general or localized deterioration is a concern with very old foundations of this type constructior or those built without consideration for the fundamentals of foundation design and waterproofing. Ideally, any repairs required should be performed in a manner consistent with existing materials.

5.1 PIERS / COLUMNS

Poor/Defective

Concrete block piers with bricks on top present.

5.2 FLOOR FRAMIMG

Poor/Defective

Floor joists are notched and hung on a 1 inch ledger and nailed to the rim joist along the front and back of the home. Their is no sill plate Upstairs Bedroom installed atop of the brick foundation and the rim joists set directly on top of the foundation.

5.3 **BEAM(S)**

Poor/Defective

Inadequate support noted for main beam; add proper support.

5.4 CRAWL SPACE VENTILATON

Poor/Defective

No/inadequate ventilation noted for the crawl space; recommend adding cross ventilation as required.

5.5 INSULATION

Poor/Defective

None present, recommend adding for improved comfort and efficiency.

5.6 VAPOR BARRIER

Poor/Defective

No vapor barrier observed in crawlspace, recommend adding to help reduce moisture and mold infiltration concerns.

5.7 WATER PENETRATION / MOISTURE

Poor/Defective

Signs of active water penetration noted around perimeter of Crawl Space. Improve exterior grading/ground slope and drainage as

required to eliminate water penetration concern. Adding gutters or roof drains that divert water away from the structure would be advisable.

Prepared Using HomeGauge http://www.HomeGauge.com : Licensed To John Murray



Table of Contents

Cover Page	<u>′</u>
General Summary	2
Table of Contents	6
Intro Page	7
<u>1 ROOFING</u>	10
2 EXTERIOR ELEMENTS	14
3 SITE ELEMENTS	18
4 INTERIOR ELEMENTS	19
5 FOUNDATION / SUBSTRUCTUR	E23



≡≡<u>EXPRESS</u>. R<u> </u>

Report ID: 1710117 / Hankinson

INSPECTION INFORMATION

CLIENT:

Ms. Dollie Hankinson

PROPERTY ADDRESS:

6810 Jefferson St Haymarket VA 20169

INSPECTION DATE/TIME:

10/11/2017 - 3:00 pm-04:00 PM

INSPECTOR:

John Murray

INSPECTION COMPANY:

Rayner Lea, LLC dba HouseMaster of Bull Run 11106 Bristow Road Bristow, Virginia 20136 571.393.3311

INSPECTION DETAILS

DESCRIPTION:AGE OF HOME:ORIENTATION:Single Family100+ yearsFacing Southeast

TYPE OF INSPECTION: STATUS OF HOME: WEATHER: Structural Element Recently Vacated Cloudy

TEMPERATURE: PEOPLE PRESENT: 75 degrees (F) Client's Agent

INTRODUCTION

The purpose of this report is to render the inspector's professional opinion of the condition of the inspected elements of the referenced property (commercial building and/or multiple dwelling) on the date of inspection. Such opinions are rendered based on the findings of a standard limited time/scope building inspection performed according to the Terms and Conditions of the Inspection Order Agreement and in a manner consistent with applicable inspection standards and customary practice.

The inspection was limited to the specified, readily visible and accessible installed major structural, mechanical and electrical elements (systems and components) of the building. The inspection does not represent a technically exhaustive evaluation and does not include any engineering, geological, design, environmental, biological, health-related or code compliance evaluations of the building or property. Furthermore, no representations are made with respect to any concealed, latent or future conditions.

The GENERAL INSPECTION LIMITATIONS on the following page provides information regarding limited time/scope building inspections, including various limitations and exclusions, as well as some specific information related to this property.

The information contained in this report was prepared exclusively for the named Clients and is not transferable without the expressed consent of the Company. The report, including all Addenda, should be reviewed in its entirety.

REPORT TERMINOLOGY

The following terminology may be used to report conditions observed during the inspection. Additional terms may also be used in the report:

SATISFACTORY - Element was functional at the time of inspection. Element was in working or operating order and its condition was at least sufficient for its minimum required function, although routine maintenance may be needed.

FAIR - Element was functional at time of inspection but has a probability of requiring repair, replacement or other remedial work at any time due to its age, condition, lack of maintenance or other factors. Have element regularly evaluated and anticipate the need to take action.

POOR - Element requires immediate repair, replacement, or other remedial work, or requires evaluation and/or servicing by a qualified specialist.

NOT APPLICABLE - All or individual listed elements were not present, were not observed, were outside the scope of the inspection, and/or were not inspected due to other factors, stated or otherwise.

NOT INSPECTED (NOT RATED) - Element was disconnected or de-energized, was not readily visible or accessible, presented unusual or unsafe conditions for inspection, was outside scope of the inspection, and/or was not inspected due to other factors, stated or otherwise. *Independent inspection(s) may be required to evaluate element conditions.* If any condition limited accessibility or otherwise impeded completion of aspects of the inspection, including those listed under LIMITATIONS, it is recommended that limiting factors be removed or eliminated and that an inspection of these elements be arranged and completed prior to closing.

IMPORTANT NOTE: All repair needs or recommendations for further evaluation should be addressed prior to closing. It is the client's responsibility to perform a final inspection to determine the conditions of the dwelling and property at the time of closing. If any decision about the property or its purchase would be affected by any condition or the cost of any required or discretionary remedial work, further evaluation and/or contractor cost quotes should be obtained prior to making any such decisions.

NATURE OF THE FRANCHISE RELATIONSHIP

The Inspection Company ("Company") providing this inspection report is a franchisee of HouseMaster LLC ("Franchisor"). As a franchisee, the Company is an independently owned and operated business that has a license to use the HouseMaster names, marks, and certain methods. In retaining the Company to perform inspection services, the Client acknowledges that Franchisor does not control this Company's

day-to-day activities, is not involved in performing inspections or other services provided by the Company, and is in no way resported to the listed Company.

GENERAL INSPECTION LIMITATIONS

CONSTRUCTION REGULATIONS - Building codes and construction standards vary regionally. A standard building inspection **does not include** evaluation of a property for compliance with building or health codes, zoning regulations or other local codes or ordinances. No assessments are made regarding acceptability or approval of any element or component by any agency, or compliance with any specific code or standard. Codes are revised on a periodic basis; consequently, existing structures generally do not meet current code standards, nor is such compliance usually required. Any questions regarding code compliance should be addressed to the appropriate local officials.

SCOPE OF INSPECTION - The scope of this standard building inspection is limited to a visual inspection and report on the physical condition of visible and readily accessible major elements of the building. The inspection was performed according to custom and practice for a limited-time scope inspection of a commercial property. Neither the inspection nor report represents an engineering evaluation or Property Condition Assessment (PCA) as defined by the American Society for Testing Materials' (ASTM) Standard Guide for Property Condition Assessments or a Phase I Environmental Assessment. These type inspections are more encompassing and technically detailed and generally also include document review, research, interviews and others actions to augment the physical inspection; and consequently would require additional time and costs to complete. Contact a Company providing these services, or any other desired inspection services, if obtaining additional information about the building's conditions is desired or has been recommended.

ENVIRONMENTAL AND MOLD ISSUES (AND EXCLUSIONS) - The potential health effects from exposure to many elements found in building materials or in the air, soil, water in and/or around any building are varied. A standard building inspection **does not include** the detection, identification or analysis of any such element or related concerns such as, but not limited to, mold, allergens, radon, formaldehyde, asbestos, lead, electromagnetic fields, carbon monoxide, insecticides, refrigerants, and fuel oils. Furthermore, no evaluations are performed to determine the effectiveness of any system designed to prevent or remove any elements (e.g., water filters or radon mitigation). An environmental health specialist should be contacted for evaluation of any potential health or environmental concerns. Review additional information on MOLD/MICROBIAL ELEMENTS below.

AESTHETIC CONSIDERATIONS - A standard building inspection does not include a determination of all potential concerns or conditions that may be present or occur in the future **including** aesthetic/cosmetic considerations or issues (appearances, surface flaws, finishes, furnishings, odors, etc.).

DESIGN AND ADEQUACY ISSUES - A standard building inspection **does not include** any element design or adequacy evaluations including seismic or high-wind concerns, soil bearing, energy efficiencies, or energy conservation measures. It also does not address in any way the function or suitability of floor plans or other design features. Furthermore, no determinations are made regarding product defects notices, safety recalls, or other similar manufacturer or public/private agency warnings related to any material or element that may be present in any building or on any property.

ESTIMATED AGES - Any age estimations represent the inspector's opinion as to the approximate age, and **are provided for general guidance purposes only**. Estimations may be based on numerous factors including, but not limited to, appearance and owner comment. Obtain independent verification if knowledge of the specific age of any element is desired or required. Age estimates are given in "years" unless noted.

DESIGN LIFE RANGE - These figures represent the typical economic service life range (in years) for elements of similar design, quality and type, as measured from the time of original construction or installation. Any stated **design life is presented solely as a guide**. It does not take into consideration abnormal, unknown, or discretionary factors, and is not a prediction of future service life.

ELEMENT DESCRIPTIONS - Any descriptions or representations of element material, type, design, size, dimensions, etc., are based primarily on visual observation of inspected or representative components. Owner comment, element labeling, listing data, and rudimentary measurements may also be considered in an effort to describe an element. However, there is no guarantee of the accuracy of any material or product descriptions listed in this report; other or additional materials may be present. Independent evaluations and/or testing should be arranged if verification of any element's makeup, design, or dimension is needed. Any questions arising from the use of any particular terminology or nomenclature in this report **should be addressed prior to closing**.

REMEDIAL WORK - Quotes should be obtained prior to closing from qualified (knowledgeable and licensed as required) specialists/ contractors to determine actual repair/replacement costs for any element or condition requiring attention. Any cost estimates provided with a standard building inspection, whether oral or written, only represent an approximation of possible costs. Cost estimates do not reflect all possible remedial needs or costs for the property; latent concerns or consequential damage may exist. **If the need for remedial work develops or is uncovered after the inspection, prior to performing any repairs contact the Inspection Company** to arrange a reinspection to assess conditions. Aside from basic maintenance suitable for the average building owner, all repairs or other remedial work should be performed by a specialist in the appropriate field following local requirements and best practices.

SELLER DISCLOSURE - This report is **not** a **substitute for Seller Disclosure**. The buyer should review Seller Disclosure information with the owner prior to closing for clarification or resolution of any questionable items. A final inspection of the building by the buyer and/or qualified representatives (prior to or at the time of closing) is also recommended.

WOOD-DESTROYING INSECTS/ORGANISMS - In areas subject to wood-destroying insect activity, it is advisable to obtain a current wood-destroying insect and organism report on the property from a qualified specialist, whether or not it is required by a lender. A standard building inspection **does not include** evaluation of the nature or status of any insect infestation, treatment, or hidden damage, nor does it cover issues related to other pests or nuisances or consequential damage.

ELEMENTS NOT INSPECTED - Any element or component not evaluated as part of this standard building inspection should be inspected prior to closing. Either make arrangements with the appropriate tradesman or contact the Inspection Company to arrange an inspection when all elements are ready for inspection.

BUILDING ORIENTATION - Location descriptions/references are provided for general guidance only and represent orientations based on a

view facing the front (street address) of the building from the outside. Any references using compass bearings are only approximathere are any questions, obtain clarification prior to closing.

BUILDING MAINTENANCE - All buildings require regular and preventive maintenance to maximize the economic life spans of elements an to minimize unanticipated repair or replacement needs. Annual maintenance costs may run 1 to 3% (or more) of the value of a building depending on age, design, and/or the degree of prior maintenance. Every building owner and maintenance personnel should develop a preventive maintenance program and budget for normal maintenance and unexpected repair expenses. Remedial work should be performe by a specialist in the appropriate field following local requirements and best practices.

MOLD AND MICROBIAL ELEMENTS / EXCLUSIONS

The purpose and scope of a standard home inspection **does not include** the detection, identification or assessment of fungi and other biological contaminants, such as molds, mildew, wood-destroying fungi (decay), bacteria, viruses, pollens, animal dander, pet or vermin excretions, dust mites and other insects. These elements contain/carry microbial particles that can be allergenic, infectious or toxic to humans, especially individuals with asthma and other respiratory conditions or sensitivity to chemical or biological contaminants. Wood-destroying fungi, some molds, and other contaminants can also cause property damage. One particular biological contamination concern is mold. Molds are present everywhere. Any type of water leakage, moisture condition or moisture-related damage that exists over a period of time can lead to the growth of potentially harmful mold(s). The longer the condition(s) exists, the greater the probability of mold growth. There are many different types of molds; most molds do not create a health hazard, but others are toxic.

Indoor mold represents the greatest concern as it can affect air quality and the health of individuals exposed to it. Mold can be found in almost all homes. Factors such as the type of construction materials and methods, occupant lifestyles, and the amount of attention given to house maintenance also contribute to the potential for molds. Indoor mold contamination begins when spores produced by mold spread by air movement or other means to an area conducive to mold growth. Mold spores can be found in the air, carpeting, insulation, walls and ceilings of all buildings. But mold spores only develop into an active mold growth when exposed to moisture. The sources of moisture in a house are numerous and include water leakage or seepage from plumbing fixtures, appliances, roof openings, construction defects (e.g., EIFS wall coverings or missing flashing) and natural catastrophes like floods or hurricanes. Excessive humidity or condensation caused by faulty fuel-burning equipment, improper venting systems, and/or inadequate ventilation provisions are other sources of indoor moisture. By controlling leakage, humidity and indoor air quality, the potential for mold contamination can be reduced. To prevent the spread of mold, immediate remediation of any water leakage or moisture problems is critical. For information on mold testing or assessments, contact a qualified mold specialist.

Neither the evaluation of the presence or potential for mold growth, nor the identification of specific molds and their effects, fall within the scope of a standard home inspection. Accordingly, the Inspection Company assumes no responsibility or liability related to the discovery or presence of any molds, their removal, or the consequences whether property or health-related.

ADDITIONAL COMMENTS

Mechanical System Upgrade Needs - No evaluations are made as part of a standard home inspection regarding heating, ventilation, or air conditioning (HVAC) system design, system efficiency, adequacy, compliance with current energy standards or costs, and other factors that may be associated with the need to or desire to repair, replace, or upgrade any equipment. If new HVAC equipment is required or desired, now or in the future, in addition to costs associated with the purchase and installation of the equipment itself, there may be additional expenses related to structural alteration or air handler and distribution system replacement or alterations. For additional information on energy efficiency requirements contact (www.doe.gov).

Pictures in Report - Any pictures (photographs, graphics, or images) included in or provided in conjunction with this Inspection Report generally portray overviews of certain elements, depict specific conditions or defects described in report comments, or are used for orientation purposes. Pictures provided do not necessarily reflect all conditions or issues that need attention or may otherwise be a concern. The inclusion of any picture is not in anyway designed to highlight or diminish the significance or severity of any defect or condition, except as may be described in the Inspection Report. The report must be read in its entirety for pertinent information.



EXPRESS. REPORT

Report ID: 1710117 / Hankinso

1. ROOFING

The inspection of roofs and rooftop elements is limited to readily visible and accessible elements as listed herein; elements and areas concealed from view for any reason cannot be inspected. This inspection does not include chimney flues and flue liners, or ancillary components or systems such as lightning protection, solar panels, and similar elements, unless specifically stated. Element descriptions are provided for general information purposes only; the verification of roofing materials, roof age, and/or compliance with manufacturer installation requirements is not within the scope of a standard home inspection. Issues related to roof or roofing conditions may also be covered under other headings in this report, including the ATTIC section.

ROOF STYLE:

Moderate Slope

ROOFING MATERIAL:

Sheet/Rolled Asphalt Standing Seam Metal

Metal

DESIGN LIFE:

Not Determined

INSPECTION METHOD:

ROOF COVERING #3:

Location: Rear Porch

Est. Age: 50+ Years

Type: Low Slope

Material: Metal

From Ground w/Binoculars

ESTIMATED AGE:

Over 50 years

ROOF COVERING #1:

Type: Moderate Slope Material: Built-up/Aggregate

Location: Front

Est. Age: 40 - 50 Years Design Life: 20 - 30 Years Insp. Method: From Ground

CHIMNEY/VENT(S):

Type: Brick Chimney Location: Center of Structure

Type: Brick Chimney

ROOF COVERING #2:

Type: Moderate Slope Material: Metal Location: Rear Est. Age: 50+ Years

Design Life: 50+ Years Insp. Method: From Ground

S F P NA NI

1.0 ROOFING Built-Up roofs by their design do not allow for visual evaluation of the water tight membrane. These roofs require special maintenance in order to remain leak free and the life expectancy varies with the quality of materials used. Therefore, no rating can be given to the roof and no evaluation was performed. Have further evaluated as desired.

1.1 ROOFING #2

Aging metal roofing noted. This material can have a lengthy service life, but requires periodic re-coating and maintenance. Have evaluated and serviced every 3-5 years by a qualified metal roofer.

• 1.2 ROOFING #3

Aging tin roofing noted. Tin can have a lengthy service life, but requires periodic re-coating and maintenance. Have evaluated and serviced every 3-5 years by a qualified metal roofer.

1.3 CHIMNEY / VENT(s)

Cracks in crown (mortar cap) noted, seal and maintain or replace as required. (Crowns typically require replacement every 10-15 yrs.)

The crown (mortar cap) of the chimney is worn. Monitor and anticipate replacement needs. (Crowns typically require replacement every 10-15 yrs.)

Mortar deterioration noted. Monitor or correct as desired.

Defective (improperly installed) flashing noted at the chimney; reseal and maintain or replace as required. Initial roof leaks and/or recurring roof leakage problems are often due to inadequate or damaged flashing. All flashings should be checked periodically or if leakage occurs. Repair or seal as needed.

1.4 RAIN GUTTERS / ROOF DRAINS

1.6 FASCIA / SOFFITS


1.5 DOWNSPOUTS


.

Decay and presence of Wood Destroying Insects noted to fascias at front, rear and sides of house, correct as required.

Deteriorated paint noted, maintenance required.


S F P NA NI S= Satisfactory, F= Fair, P= Poor/Defective, NA= Not Applicable, NI= Not Inspected






1.3 CHIMNEY / VENT(s) (Picture 1)





1.3 CHIMNEY / VENT(s) (Picture 2)

1.3 CHIMNEY / VENT(s) (Picture 3)





1.3 CHIMNEY / VENT(s) (Picture 4)

1.3 CHIMNEY / VENT(s) (Picture 5)



1.6 FASCIA / SOFFITS (Picture 1)



1.6 FASCIA / SOFFITS (Picture 2)



1.6 FASCIA / SOFFITS (Picture 3)




1.6 FASCIA / SOFFITS (Picture 4)





1.6 FASCIA / SOFFITS (Picture 5)

1.6 FASCIA / SOFFITS (Picture 6)



1.6 FASCIA / SOFFITS (Picture 7)

NOTE: All roofs have a finite life and will require replacement at some point. In the interim, the seals at all roof penetrations and flashings, and the watertightness of rooftop elements, should be checked periodically and repaired or maintained as required. Any roof defect can result in leakage, mold, and subsequent damage. Conditions such as hail damage or manufacturing defects or whether the proper nailing methods or underlayment were used are not readily detectible during a home inspection. Gutters (eavestroughs) and downspouts (leaders) will require regular cleaning and maintenance. All chimneys and vents should be checked periodically. In general, fascia and soffit areas are not readily accessible for inspection; these components are prone to decay, insect, and pest damage, particularly with roof or gutter leakage. If any roof deficiencies are reported, a qualified roofer or the appropriate specialist should be contacted to determine what remedial action is required. If the roof inspection was restricted or limited due to roof height, weather conditions, or other factors, arrangements should be made to have the roof inspected by a qualified roofer, particularly if the roofing is older or its age is unknown.



EXPRESS. REPORT

Report ID: 1710117 / Hankinson

2. EXTERIOR ELEMENTS

Inspection of exterior elements is limited to readily visible and accessible surfaces of the house envelope and connected appurtenances as listed herein; elements concealed from view by any means cannot be inspected. All exterior elements are subject to the effects of long-term exposure and sudden damage from ongoing and ever-changing weather conditions. Style and material descriptions are based on predominant/representative components and are provided for general information purposes only; specific types and/or material make-up material is not verified. Neither the efficiency nor integrity of insulated window units can be determined. Furthermore, the presence/condition of accessories such as storms, screens, shutters, locks and other attachmen or decorative items is not included, unless specifically noted. Additional information on exterior elements, particularly windows/doors and the foundation may be provided under other headings in this report, including the INTERIOR and FOUNDATION/SUBSTRUCTURE sections.

SIDING / WALL STRUCTURE #1 - TYPE:

SIDING #1 - LOCATION:

Wood


Whole House

S F P NA NI


•		Surfaces on older homes may have layers of lead-based paint, particularly pre-1978 paint applications. Th likelihood of exposure to lead hazards is minimal if the paint is intact or covered with another produc Neither testing nor assessment is part of a standard home inspection. Testing by a qualified specialist shoul be arranged if paint damage or other potential hazards exist or to address individual concerns. Paint i deteriorated; maintain as required. Siding has several holes from damage and prior renovations.	
•		be arranged if paint damage or other potential hazards exist or to address individual concerns. Paint i deteriorated; maintain as required. Siding has several holes from damage and prior renovations.	
•	-		
•			
	1	2.1 WINDOWS	
1800		All windows are boarded up and rotting around the sills.	
•		2.2 ENTRY DOORS	
Moisture damage noted to jamb/frame at Front Entry, correct as required. Any damage should be c addressed properly to minimize consequential damage or further infestation.			
2.3 STAIRS / STOOPS		2.3 STAIRS / STOOPS	
		Deteriorated stoop noted at Front Entry; repair/replace as required.	
		No handrail at the stoop at the Front Entry; recommend adding for safety.	
2.4 RAILINGS			
•		2.5 FOUNDATION SURFACE	
		Deteriorated bricks and mortar noted in curtain/veneer wall at front, rear and sides of house, have area repointed by a qualified brick mason.	
		2.6 ELECTRICAL / GFCI	
		Power was not available to the house; romex wiring is aged, no outside Outlets installed, lighting wires/bulbs are bare. Replace wiring and install Fixtures.	
		•	

S F P NA NI S= Satisfactory, F= Fair, P= Poor/Defective, NA= Not Applicable, NI= Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Please contact the Company for clarification on ratings or findings if there are any questions.



2.0 SIDING / WALL CLADDING (Picture 1)



2.0 SIDING / WALL CLADDING (Picture 2)



1 Expanded Right Wall

2.0 SIDING / WALL CLADDING (Picture 3)

2.0 SIDING / WALL CLADDING (Picture 4)



2.0 SIDING / WALL CLADDING (Picture 5)



2.0 SIDING / WALL CLADDING (Picture 6)



2.0 SIDING / WALL CLADDING (Picture 7)




2.0 SIDING / WALL CLADDING (Picture 8)






2.2 ENTRY DOORS (Picture 1)


2.2 ENTRY DOORS (Picture 2)




2.3 STAIRS / STOOPS (Picture 1)



2.5 FOUNDATION SURFACE (Picture 1)



2.6 ELECTRICAL / GFCI (Picture 1)



2.6 ELECTRICAL / GFCI (Picture 2)



2.6 ELECTRICAL / GFCI (Picture 3)

NOTE: All surfaces of the envelope of the house should be inspected at least semi-annually, and maintained as needed. Any exterior element defect can result in leakage and/or subsequent damage. Exterior wood elements and wood composites are particularly susceptible to water-related damage, including decay, insect infestation, and mold. The use of proper treated lumber or alternative products may help minimize these concerns, but will not eliminate them altogether. While some areas of decay or damage may be reported, additional areas of concern may exist, subsequently develop, or be discovered during repair or maintenance work. Should you wish advice on any new or uncovered area of deterioration, please contact the Inspection Company. Periodic caulking/resealing of all gaps and joints will be required. Insulated window/door units are subject to seal failure, which could ultimately affect the transparency and/or function of the window. Lead-based paints were commonly used on older homes; independent inspection is required if confirmation or a risk assessment is desired.



EXPRESS. REPORT

Report ID: 1710117 / Hankinsc-

3. SITE ELEMENTS

Inspection of site elements is primarily intended to address the condition of listed, readily visible and accessible elements immediately adjacent to or surrounding the house for conditions and issues that may have an impact on the house. Elements and areas concealed from view for any reason cannot be inspected. Neither the inspection nor report includes any geological surveys, soil compaction surveys, ground testing, or evaluation of the effects of, or potential for, earth movement such as earthquakes, landslides, or sinking, rising or shifting for any reason. Information on local soil conditions and issues should be obtained from local officials and/or a qualified specialist prior to closing. In addition to the stated limitations on the inspection of site elements, a standard home inspection does not include evaluation of elements such as underground drainage systems, site lighting, irrigation systems, barbecues, sheds, detached structures, fencing, privacy walls, docks, seawalls, pools, spas and other recreational items. Additional information related to sit element conditions may be found under other headings in this report, including the FOUNDATION/SUBSTRUCTURE and WATER PENETRATION sections.

S F P NA NI

	•	3.0 PATIO(S)
	•	3.1 WALKWAYS
	•	3.2 DRIVEWAY
•		3.3 GROUND SLOPE AT FOUNDATION Negative grade noted at front, rear and sides of house; correct as required to help reduce water penetration and potential settlement concerns.
•		3.4 SITE GRADING Grading slopes towards the house at front, rear and sides of house; monitor runoff and correct as needed.

S F P NA NI S= Satisfactory, F= Fair, P= Poor/Defective, NA= Not Applicable, NI= Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Please contact the Company for clarification on ratings or findings if there are any questions.

NOTE: Site conditions are subject to sudden change with exposure to rain, wind, temperature changes, and other climatic factors. Roof drainage systems and site/foundation grading and drainage must be maintained to provide adequate water control. Improper/inadequate grading or drainage and other site factors can cause or contribute to foundation movement or failure, water infiltration into the house interior, and/or mold concerns. Independent evaluation by an engineer or soils specialist is required to evaluate geological or soil-related concerns. Houses built on expansive clays or uncompacted fill, on hillsides, along bodies of water, or in low-lying areas are especially prone to structural concerns. All improved surfaces such as patios, walks, and driveways must also be maintained to drain water away from the foundation. Any reported or subsequently occurring deficiencies must be investigated and corrected to prevent recurring or escalating problems. Independent evaluation of ancillary and site elements by qualified servicepersons is recommended prior to closing.



EXPRESS. REI ON

Report ID: 1710117 / Hankinson

4. INTERIOR ELEMENTS

Inspection of the house interior is limited to readily accessible and visible elements as listed herein. Elements and areas that are inaccessible or conceale from view by any means cannot be inspected. Aesthetic and cosmetic factors (e.g., paint and wallpaper) and the condition of finish materials and covering are not addressed. Window and door evaluations are based on a random sampling of representative units. It is not possible to confirm safety glazing or the efficiency and integrity of insulated window/door units. Auxiliary items such as security/safety systems (or the need for same), home entertainment or communication systems, structured wiring systems, doorbells, telephone lines, central vacuums, and similar components are not included in a standard home inspection. Due to typical design restrictions, inspection of any fireplace, stove, or insert is limited to external conditions. Furthermore, such inspection addresses physical condition only; no code/fire safety compliance assessment or operational check of vent conditions is performed. Additional information or interior elements may be provided under other headings in this report, including the FOUNDATION/SUBSTRUCTURE section and the major house systems.

CEILING TYPE(S):

Wood Frame Plaster

Gypsum board
WINDOW TYPE(S):
Double Huna

WALL TYPE(S):

Wood Frame Wood Frame Interior Walls Gypsum board

SMOKE DETECTOR(S):

Not Present/Observed

FLOOR TYPE(S):

Wood Frame w/ hardwood floors

CARBON MONOXIDE DETECTOR(S):


None Observed

S F P NA NI

		•		4.0 CEILINGS / STRUCTURE
				Water damage noted at Upstairs Bedroom; repair as required.
Hole in ceiling noted at Upstairs Bedroom, repair as required.				Hole in ceiling noted at Upstairs Bedroom, repair as required.
				There is a potential that exterior and/or interior surfaces are covered with a lead-based paint, particularly i pre-1978 homes. If paint is intact or covered with another product the likelihood of the release of any significar lead is minimized. No lead-based paint assessment is made as part of a standard home inspection. Individuation concerns should be considered and testing by a qualified specialist can be arranged if needed.
П		•	1	4.1 WALLS / STRUCTURE
	Evidence of many prior repairs noted. There is a potential that exterior and/or interior surfaces are covered with a lead-based paint, particularly in pre-1978 homes. If paint is intact or covered with another product the likelihood of the release of any significant lead is minimized. No lead-based paint assessment is made as pa of a standard home inspection. Individual concerns should be considered and testing by a qualified specialis can be arranged if needed.			with a lead-based paint, particularly in pre-1978 homes. If paint is intact or covered with another product the likelihood of the release of any significant lead is minimized. No lead-based paint assessment is made as part of a standard home inspection. Individual concerns should be considered and testing by a qualified specialist
H			+	4.2 FLOORS (FRAMED)
	and the same			Damaged flooring; repair as required.
4.3 STAIRS/STEPS		\top	4.3 STAIRS/STEPS	
				No handrail noted; add for safety.
				Low headroom noted at stairway entry. Exercise caution.
4.4 RAILINGS		4.4 RAILINGS		
		No handrail noted at second story stairs; add for safety.		
П	•			4.5 WINDOWS
				Defective retention springs/ballast weights noted at , Kitchen Living Room Guest Bed Room Small Bed Room. Correct as required.
				Cracked panes noted at Kitchen Living Room Guest Bed Room Small Bed Room; replace as required.
				General maintenance needed.
				Older single glaze windows noted. Glazing and other maintenance required.
	4.6 ROOM DOORS		4.6 ROOM DOORS	
				Older and missing doors, anticipate maintenance and adjustment needs.

S F P NA NI S= Satisfactory, F= Fair, P= Poor/Defective, NA= Not Applicable, NI= Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Please contact the Company for clarification on ratings or findings if there are any questions.





4.0 CEILINGS / STRUCTURE (Picture 1)

4.0 CEILINGS / STRUCTURE (Picture 2)





4.0 CEILINGS / STRUCTURE (Picture 3)

4.0 CEILINGS / STRUCTURE (Picture 4)





4.0 CEILINGS / STRUCTURE (Picture 5)

4.0 CEILINGS / STRUCTURE (Picture 6)



4.0 CEILINGS / STRUCTURE (Picture 7)



4.0 CEILINGS / STRUCTURE (Picture 8)



4.0 CEILINGS / STRUCTURE (Picture 9)



4.0 CEILINGS / STRUCTURE (Picture 10)



4.0 CEILINGS / STRUCTURE (Picture 11)



4.1 WALLS / STRUCTURE (Picture 1)




4.1 WALLS / STRUCTURE (Picture 2)




4.1 WALLS / STRUCTURE (Picture 3)



4.2 FLOORS (FRAMED) (Picture 1)



4.5 WINDOWS (Picture 1)



4.5 WINDOWS (Picture 2)

NOTE: All homes are subject to indoor air quality concerns due to factors such as venting system defects, outgassing from construction materials, smoking, and the use of house and personal care products. Air quality can also be adversely affected by the growth of molds, fungi and other micro-organisms as a result of leakage or high humidity conditions. If water leakage or moisture-related problems exist, potentially harmful contaminants may be present. A home inspection does not include assessment of potential health or environmental contaminants or allergens. For air quality evaluations, a qualified testing firm should be contacted. All homes experience some form of settlement due to construction practices, materials used, and other factors. A pre-closing check of all windows, doors, and rooms when house is clear of furnishings, drapes, etc. is recommended. If the type of flooring or other finish materials that may be covered by finished surfaces or other items is a concern, conditions should be confirmed before closing. Lead-based paint may have been used in the painting of older homes. Chimney and fireplace flue inspections should be performed by a qualified specialist. Regular cleaning is recommended. An assessment should be made of the need for and placement of detectors. All smoke and carbon monoxide detectors should be tested on a regular basis.



EXPRESS. REPORT

Report ID: 1710117 / Hankinson

5. FOUNDATION / SUBSTRUCTURE

The inspection of the substructure and foundation is limited to readily visible and access elements as listed herein. Elements or areas concealed from view for any reason cannot be inspected. In most homes, only a representative portion of the structure can be inspected. Any element description provided is for general information purposes only; the specific material type and/or make-up cannot be verified. Neither the inspection nor report includes geological surveys, soil compaction studies, ground testing, evaluation of the effects of or potential for earth movement such as earthquakes, landslides, or sinking, rising or shifting for any reason, or verification of prior water penetration or predictions of future conditions. Furthermore, a standard home inspection is not a wood-destroying insect inspection, an engineering evaluation, a design analysis, or a structural adequacy study, including that related to high-wind or seismic restraint requirements. Additional information related to the house structure may be found under many other headings in this report.

CRAWLSPACE:

CRAWLSPACE INSPECTION METHOD:

FOUNDATION WALLS/PIERS:

Full House Entered

Brick

HOUSE FLOOR STRUCTURE: *Wood Frame*

INSULATION:

None

VAPOR RETARDER(S):

Truss

None


S F P NA NI

of brick, reducing them to a sandy powder This deterioration can be slowed, and effect to the walls. Recommend coating walls to The potential for general or localized construction or those built without			5.0 FOUNDATION / SUBSTRUCTURE A condition known as spalling was noted in the bricks of the foundation walls. Spalling is the slow deterioration of brick, reducing them to a sandy powder, as the effects of time, moisture, and other factors take their toll. This deterioration can be slowed, and effected walls stabilized by applying a surface "parge" coat of concrete to the walls. Recommend coating walls to control spalling and maintain structural integrity of foundation. The potential for general or localized deterioration is a concern with very old foundations of this typ construction or those built without consideration for the fundamentals of foundation design an waterproofing. Ideally, any repairs required should be performed in a manner consistent with existing materials		
		•		5.1 PIERS / COLUMNS	
				Concrete block piers with bricks on top present.	
	5.2 FLOOR FRAMIMG Floor joists are notched and hung on a 1 inch ledger and nailed to the rim joist along the front and back home. Their is no sill plate Upstairs Bedroom installed atop of the brick foundation and the rim joists set directly on top of the foundation.				
5.3 BEAM(S) Inadequate support noted for main beam; add proper support.					
		•		5.4 CRAWL SPACE VENTILATON No/inadequate ventilation noted for the crawl space; recommend adding cross ventilation as required.	
		•		5.5 INSULATION None present, recommend adding for improved comfort and efficiency.	
		•	5.6 VAPOR BARRIER No vapor barrier observed in crawlspace, recommend adding to help reduce moisture and mold infiltration concerns.		
		•		5.7 WATER PENETRATION / MOISTURE Signs of active water penetration noted around perimeter of Crawl Space. Improve exterior grading/ground slope and drainage as required to eliminate water penetration concern. Adding gutters or roof drains that divert water away from the structure would be advisable.	

S F P NA NI S= Satisfactory, F= Fair, P= Poor/Defective, NA= Not Applicable, NI= Not Inspected


Review REPORT TERMINOLOGY on Introduction Page. Please contact the Company for clarification on ratings or findings if there are any questions.






5.0 FOUNDATION / SUBSTRUCTURE (Picture 1)

5.1 PIERS / COLUMNS (Picture 1)





5.2 FLOOR FRAMIMG (Picture 1)

5.3 BEAM(S) (Picture 1)

NOTE: All foundations are subject to settlement and movement. Improper/inadequate grading or drainage can cause or contribute to foundation damage and/or failure and water penetration. Deficiencies must be corrected and proper grading/drainage conditions must be maintained to minimize foundation and water penetration concerns. If significant foundation movement or cracking is indicated, evaluation by an engineer or qualified foundation specialist is recommended. All wood components are subject to decay and insect damage; a wood-destroying insect inspection is recommended. Should decay and/or insect infestation or damage be reported, a full inspection should be made by a qualified specialist to determine the extent and remedial measures required. Insulation and other materials obstructing structural components are not normally moved or disturbed during a home inspection. Obstructed elements or inaccessible areas should be inspected when limiting conditions are removed. In high-wind or high-risk seismic areas, it would be advisable to arrange for an inspection of the house by a qualified specialist to determine whether applicable construction requirements are met or damage exists. Should you seek advice or wish to arrange a new inspection for elements not visible during the inspection, please contact the Inspection Company.

SALES CONTRACT FOR UNIMPROVED LAND

T	his SALES CON	FRACT ("Contract") is made on 10/0	8/2017	("Date of Offer")
		laca and Maria Vilaca		("Buyer") and
		Scott H. Donovan for Jean Rosemand Leo		("Seller")
		things, hereby confirm and acknowled		s and signatures herein
		sure in this real estate transaction RE/		
		e") represents Seller, and REMAX Gate		
		xerage") represents ☐ Buyer or ☑ S		
BI	okerage are colle	ectively referred to as Broker. (If the	brokerage firm is a	acting as a dual
m	presentative for b	oth Seller and Buyer, then the appro	priate disclosure fo	orm is attached to and
he	low and other or	Contract.) In consideration of the mood and valuable consideration the re	utual promises and	covenants set forth
		parties agree as follows:	ceipt and sufficien	icy of which is
	(190)	5 3 44 75 40 250376 500774 500776 500776 500776	or across to sall the	land and all
1.	improvements t	ERTY. Buyer agrees to buy and Sello hereon located in the County or City	of Town of Harman	rat VA
	Virginia and de	scribed as (legal description): Tax Ma	on 44064. TM 7297-88	5078
	8	regar description). Tax in	ip 11001, 1111 1251 00	3070
			("Property"), cont	taining (more or less)
		square feet or acre and also known	own as (property ac	ddress) if applicable:
		et, Haymarket, VA 20169		, together with the
		in the IMPROVEMENTS, CHATT	ELS AND/OR EQI	UIPMENT
^	INCLUDED par			
2.	IMPROVEME	NTS, CHATTELS AND/OR EQU	IPMENT INCLU	DED . The following
	items are includ	ed in this sale: existing building		
3.	DDICE AND E	INANCING This sale shall be:	1 11	1 1
Э,		INANCING. ✓ This sale shall be in the exact sales price OR ☐ the purch		
	to an exact pure			are feet OR per
		area to be determined by a survey to		
	for by:	and the second s	or made by a neon	
	A. Down Paym	ent	\$	or %
	B. Financing	1. First Trust (if applicable)	\$	or %
	8	2. Second Trust (if applicable)		or %
		3. Seller Held Trust	\$ \$	or %
				01 /0
	TOTAL DIS	Addendum attached (if applicable		0.7
	TOTAL FIR		\$ 50000	or %
	SALES PRI		\$ \$80000	
		f Trust. Buyer will Obtain OR		
		rate First Deed of Trust loan amortiz		
	The state of the s	t an (initial) interest rate not to excee		
		onal See Addendum Attached	□ VA See	Addendum Attached
	☐ FHA	See Addendum Attached	Other: Land,	Construction, Permanen
	☐ This contr	act is not contingent on Financing.		
	D. Second Deed	l of Trust. Buyer will Dobtain Ol	R □ Assume a □ F	ixed OR an □
		ate Second Deed of Trust loan.		

- **27. VOID CONTRACT.** If this Contract becomes void and of no further force and effect, without Default by either party, both parties will immediately execute a release directing that the Deposit be refunded in full to Buyer according to the terms of the DEPOSIT paragraph.
- 28. TIME IS OF THE ESSENCE AS TO ALL TERMS OF THIS AGREEMENT.

	ntract shall preclude arbitration under the Code of National Association of REALTORS®.				
30. REAL ESTATE LICENSED PART insurance, title insurance, mortgage los estate-related businesses and services, course of this transaction, in addition to that Broker is retained for their real est as an attorney, tax advisor, appraiser, to other professional service provider.	IES. Broker may from time to time engage in general an, real estate settlement, home warranty and other real from which they may receive compensation during the o real estate brokerage fees. The parties acknowledge ate brokerage expertise, and neither has been retained itle advisor, home inspector, engineer, surveyor, or is an □ active or □ inactive licensed real and is either the □ Buyer □ Seller or □ is				
respective heirs, executors, administrat not satisfied at Settlement will survive therein. This Contract, unless amended the parties and the parties will not be be	ract will be binding upon the parties, and each of their ors, successors and permitted assigns. The provisions the delivery of the deed and will not be merged in writing, contains the final and entire agreement of ound by any terms, conditions, oral statements, a contained. The interpretation of this Contract will be realth of Virginia.				
	f ratified and attached, are made a part of this of addenda that may need to be attached).				
	lum				
33. DISCLOSURE OF SALES PRICE TO APPRAISER Listing Brokerage and Cooperating Brokerage are hereby authorized to release the Sales Price listed in PRICE AND SPECIFIED FINANCING Paragraph to any appraiser who contacts them to obtain the information.					
	r 60 days upon obtaining demolition approval of the Leonard				
House on the property from the Town of Hays 2. One prepaid sewer tap is included in the sa					
SELLER:	BUYER:				
Dollie Hankinson dottoop verified 20117/17 931PM EDT 27MQ-2KAO-6PPI-MZTM	dotloop verified Feliciano Vilaca 10/17/17 3:36PM EDT TQHY-RRVU-KHVT-HXST				
Date Signature	Date Signature				
dotloop verified 10/17/17 12:08PM EDT LAM2-LHPY-BZV4-VS8H	Maria Vilaca dutoop verified 10/18/17 6:51PM EDT WWB4-NMNO-ORBS-KMGN				
Date Signature	Date Signature				

NVAR - K1209 - rev. 01/17

Date of Ratification 10/18/2017